

RECORD INFORMATION & WITNESS DETAILS	
Witness(es) Present:	N/A
Photographs Taken By:	Eric Morofuji, EHS III
FACILITY / SITE & PHOTOGRAPH DETAILS	
Date Photograph(s) Taken:	2/13/24
DBA / Location Name:	Chiquita Canyon Landfill
Location Address:	29201 Henry Mayo Drive, Castaic, CA 91384



View of:	<p>Heavy erosion observed on slope located at the reaction area. For your reference, the pump at the top of the slope is #1966.</p> <p>.</p>
----------	--

RECORD INFORMATION & WITNESS DETAILS	
Witness(es) Present:	N/A
Photographs Taken By:	Eric Morofuji
FACILITY / SITE & PHOTOGRAPH DETAILS	
Date Photograph(s) Taken:	2/13/24
DBA / Location Name:	Chiquita Canyon Landfill
Location Address:	29201 Henry Mayo Drive, Castaic 91384



View of:	Heavy erosion looking down the slope located at the reaction area.
----------	--

RECORD INFORMATION & WITNESS DETAILS	
Witness(es) Present:	N/A
Photographs Taken By:	Eric Morofuji, EHS III
FACILITY / SITE & PHOTOGRAPH DETAILS	
Date Photograph(s) Taken:	2/13/24
DBA / Location Name:	Chiquita Canyon Landfill
Location Address:	29201 Henry Mayo Drive, Castaic, CA 91384



View of:	Heavy erosion observed on slope located in the reaction area.
----------	---