SECTION CORNER
Found 24"x12"x8" sandstone, marked with 3 notches on South edge and 1 notch on East edge, per C.S.9174-4, C.S.8843 and C.S.8807-2. Replaced 24"x12"x8" sandstone with 2" iron pipe, 24" in concrete, with brass cap marked "This replacement was made by the county surveyor in Aug 1926. F.B. 41-69-110-123.

1/4 SECTION CORNER
A piece of yellow sandstone, marked with 1/4 was found at this point in a stone mound. The sandstone was not found at this point when the line was run in September 1925, however the stone mound was. While the sandstone is apparently not an original corner, the mound has existed for many years and is generally accepted by the settlers as the 1/4 Section Corner. Set 2" iron pipe in concrete with brass cap marked—F.B.111-67-116-136

SECTION CORNER
Found 24"x12"x8" sandstone marked with 3 notches on South face and 3 notches on North face per C.S.9174-1 and C.S.8834. Replaced 24"x12"x8" sandstone with 2" iron pipe set in concrete with brass cap marked—F.B.111-117-118

1/4 SECTION CORNER
Found 24"x8"x8" sandstone, in mound of rocks marked "1/4 on West face per C.S.9174-2 and C.S.8834. Replaced 24"x8"x8" sandstone with 2" iron pipe, set in concrete with brass cap marked—F.B.111-118-119-122-125

1/4 SECTION CORNER
Found 24"x8"x8" sandstone marked 1/4 on East face per C.S.9174-4, C.S.8807-2 and C.S.8843. Replaced 24"x8"x8" sandstone with 2" iron pipe set in concrete with brass cap marked—F.B.111-118-119-122-124

CENTER OF SECTION
Located by intersection. Nothing set.

1/4 SECTION CORNER
Found hole in top of 24"x12"x8" sandstone per C.S.9174-3 and C.S.8834. Replaced 24"x12"x8" sandstone with 2" iron pipe set in concrete with brass cap marked—F.B.111-119-111-121

SECTION CORNER
Found sandstone marked with 4 notches on South side and 1 notch on East side per C.S.9174-4, C.S.8834, F.B.111-114-117 and F.B.111-33-33. Replaced sandstone with 2" iron pipe set in concrete with brass cap marked—F.B.111-117-118

SECTION CORNER
Found sandstone boulder marked with 2 notches on South side and 4 notches on North side. Stone mound alongside per C.S.9174-2 and C.S.8834. Also found 2" iron pipe against Northeast side per C.S.8834. Removed sandstone boulder and 2" iron pipe. Replaced sandstone boulder with 2" iron pipe set in concrete with brass cap marked—F.B.111-118-116

MAP OF
SECTION 24, T. 1 S., R. 17 W. S.B.M.

COUNTY SURVEYORS MAP Nº B-525
SCALE-1 INCH=200 FT.

WORK ORDER Nº 523

J.E. ROCKHOLD - COUNTY SURVEYOR
SURVEYED AUG. TO OCT. 1929

SURVEYED UNDER INSTRUCTIONS OF THE BOARD OF SUPERVISORS PER ORDER DATED DECEMBER 19, 1925.
BEARINGS ARE BASED ON THE BEARING OF THE WESTERLY LINE OF THE NORTHWEST 1/4, SECTION 24, T. 1 S., R. 17 W. PER C.S. 8843

F.B. 111-106-136

FIELD WORK BY A. BRACKETT
" " " F.C. HOWARD
OFFICE WORK BY BERT McATEE
CHECKED BY D.M. FINLEY

Sht. 89

CSB-525
A1 OF A1