Notes Ck'd by		Survey of	F.B. 3031 Pg.
Map No.		JN Tape Std °F	
Office Work		Surveyed by	
Checked		Notes Date	
Date		Indexed	

PAGES		TRACT #
5	31	27065
6-11	31	27034
12-19		26168
20-23		25222
24-29		26160
30	31	20748
31	31	25500
32-39		26793
40-49		26697
50-68	31	25109
69-74	31	26414
75-91	31	25106
92-104		26307

3031

CO. ENGR. F.B. 3031: 5

SURVEY OF _____ F B NO. _____ PAGE _____

SURVEY BY Charles C. Miller, R.E. 122 TRACT NO 27065

DATE 1-3-63



CO. ENGR. F.B. 3031: 6

SURVEY OF CENTERLINE TIES F. B. 27034 Pg. 1

SURVEY BY McDANIEL ENGINEERING Co TR. No. 27034

DATE OCT. 29, 1962

NOTE: ALL TAGS ARE L.S. 2988

W.S. 28A-4



CO. ENGR. F.B. 3031: 7

F. B. 27034 PG. 2 SURVEY OF CENTERLINE TIES

TR. No. 27034 SURVEY BY Mc DANIEL ENGINEERING CO.

DATE OCT. 25, 1962



CO. ENGR. F.B. 3031:~~8~~

SURVEY OF CENTERLINE TIES F. B. 27034 Pg. 3

SURVEY BY McDANIEL ENGINEERING Co TR. No. 27034

DATE OCT. 25, 1962



SEE PAGE 2

CO. ENGR. F.B. 3031: 9

F. B. 27034 PG. 4 SURVEY OF Centerline Ties

TR. No. 27034 SURVEY BY McDaniel Engineering Co

DATE Oct. 25, 1962

W.S. 38A-4



CO. ENGR. F.B. 3031:10

SURVEY OF Centerline Ties — F. B. 27034 Pg. 5

SURVEY BY Mc Daniel Engineering Co. — TR. No. 27034

DATE Oct. 25, 1962



SEE SHEET 4

CO. ENGR. F.B. 3031: 11

F. B. 27034 PG. 6 SURVEY OF CENTERLINE TIES

TR. NO. 27034 SURVEY BY McDANIEL ENGINEERING CO.

DATE OCT. 25, 1962



CO. ENGR. F.B. 3031:12

SURVEY OF ℄ Monuments ℄ Ties F. B. Pg.

SURVEY BY Development Consultants TR. No. 26168

DATE 12-29-62 Sheet 1 of 8

Sheet 2



CO. ENGR. F.B. 3031: 13

F. B. _____ Pg. _____ SURVEY OF ℄ Monuments & Ties

TR. No. 26168 SURVEY BY Development Consultants

Sheet 2 of 8 DATE 12-29-62



WS-38, D-4 099-317, A-2

CO. ENGR. F.B. 3031: 14

SURVEY OF ℄ Monuments & Ties F. B. ____ PG. ____

SURVEY BY Development Consultants TR. No. 26168

DATE 12-29-62

Sheet 3 of 8



099-317A-2 MS 38 D-4

CO. ENGR. F.B. 3031: 15

F. B. _____ Pg. _____ SURVEY OF ℄ Monuments & Ties

TR. No. 26168 SURVEY BY Development Consultants

Sheet 4 of 8 DATE 12-29-62



CO. ENGR. F.B. 3031: 16

SURVEY OF ℄ Monuments & Ties F. B. Pg.

SURVEY BY Development Consultants TR. No. 26168

DATE 12-29-62

Sheet 7 of 8



4-D'38'S'M 2-4'13-660

CO. ENGR. F.B. 3031: 17

F. B. _____ PG. _____ SURVEY OF ℄ Monuments & Ties

TR. No. 26168 SURVEY BY Development Consultants

Sheet 8 of 8 DATE 12-29-62

Sheet 7



CO. ENGR. F.B. 3031: 18

SURVEY OF ℄ Monuments & Ties F. B. _____ PG. _____

SURVEY BY Development Consultants TR. No. 26168

DATE 12-29-62

Sheet 5 of 8



C99-317A-1 4538, D-4

CO. ENGR. F.B. 3031: 19

F. B. _____ Pg. _____ SURVEY OF ℄ Monuments & Ties

TR. No. 26168 SURVEY BY Development Consultants

Sheet 6 of 8 DATE 12-29-62



W538 D-4

099-317, A-2

CO. ENGR. F.B. 3031: 20

SURVEY OF ℄ TIES — F. B. — Pg.

SURVEY BY POND ENGINEERING CO. — TR. No. 25222

DATE January 8, 1963



CO. ENGR. F.B. 3031: 21

F. B. _____ Pg. _____ SURVEY OF 6 TIES

TR. No. 25222 SURVEY BY POND ENGINEERING CO.

DATE January 8, 1963



CO. ENGR. F.B. 3031: 22 •

SURVEY OF ℄ TIES F. B. Pg.

SURVEY BY POND ENGINEERING CO. TR. No. 25222

DATE January 8, 1963



CO. ENGR. F.B. 3031: 23

F. B. _____ PG. _____ SURVEY OF ℄ TIES

TR. No. 25222 SURVEY BY POND ENGINEERING CO.

DATE January 8, 1963



CO. ENGR. F.B. 3031: 24

SURVEY OF ℄ Monuments & Ties F. B. Pg.

SURVEY BY Development Consultants TR. No. 26160

DATE 12-14-62 Sheet 5 of 6

Sheet 3



CO. ENGR. F.B. 3031: 25

F. B. _____ PG. _____ SURVEY OF ℄ Monuments & Ties

TR. No. 26160 SURVEY BY Development Consultants

Sheet 6 of 6 DATE 12-14-62



CO. ENGR. F.B. 3031: 26

SURVEY OF ℄ Monuments & Ties F. B. Pg

SURVEY BY Development Consultants TR. No. 26160

DATE 12-14-62

Sheet 3 of 6



CO. ENGR. F.B. 3031: 27

F. B. _____ PG. _____ SURVEY OF ℄ Monuments & Ties

TR. No. 26160 SURVEY BY Development Consultants

DATE 12-14-62

Sheet 4 of 6



WS38 D-4

099-317/A-2

CO. ENGR. F.B. 3031: 28

SURVEY OF ℄ Monuments & Ties F. B. _____ PG. _____

SURVEY BY Development Consultants TR. No. 26160

DATE 12-14-62

Sheet 1 of 6



WS 38 D-4

WS 099-317 A-1

CO. ENGR. F.B. 3031: 29

F. B. _____ Pg. _____ SURVEY OF ℄ Monuments & Ties

TR. No. 26160 SURVEY BY Development Consultants

Sheet 2 of 6 DATE 12-14-62



Sheet 1

CO. ENGR. F.B. 3031: 30

SURVEY OF ℄ Ties & Blue Border Monuments F. B. _____ PG. _____

SURVEY BY Hillcrest Engineering Corp. TR. No. 20748

DATE January 9, 1963



CO. ENGR. F.B. 3031: 31

SURVEY OF TRACT No 25500 F B NO. ____ PAGE ____

SURVEY BY National Engineering Co. TRACT NO. 25500

DATE JAN '16 1963



114-277 C-3

4537 E-3

CO. ENGR. F.B. 3031: 32

SURVEY OF _____ F. B. _____ Pg. _____

SURVEY BY _____ TR. No. 26793

DATE November, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838



NOTE:
N.f.T. Indicates Set Nail & Tag Mrk'd. R.C.E. 8244 in Concrete.

CO. ENGR. F.B. 3031: 33

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26793

DATE November 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838

NOTE:
N.&T.→o Indicates Set Nail & Tag Marked: R.C.E. 8244 in Except as Note



W.S. 377, D-2

CO. ENGR. F.B. 3031: 34

OF _____ F. B. _____ PG. _____

BY _____ TR. No. 26793

November, 1962

EN ENGINEERING, INC.
5 E. WHITTIER BLVD.
. Box 1547, Perry Annex
er, Calif. Phone: 691-0838



NOTE:
℄T. → Ind. Set Nail & Tag
Mrk'd R.C.E. 8244
in Conc.

CO. ENGR. F.B. 3031: 35

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26793

DATE November, 1962

THOMSEN ENGINEERING
16145 E. WHITTIER BL
P.O. Box 1547 Perry Ann
Whittier, Calif. Phone: 691-



NOTE:
N.C.T. ⊸ Indicates Set Nail & Tag
Marked R.C.E. 8244 in Conc.

CO. ENGR. F.B. 3031: 36

OF _____ F. B. _____ PG. _____

BY _____ TR. No. 26793

November, 1962

N ENGINEERING, INC.
E. WHITTIER BLVD.
Box 1547 Perry Annex
Calif. Phone: 691-0838



OTE:

o Indicates Set Nail & Tag Marked R.C.E. 8244 in Conc.

2-9 LESM

CO. ENGR. F.B. 3031: 37

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26793

DATE November, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838



Note:
N.C.T.—o Indicates Set Nail & Tag
Marked R.C.E. 8244 in Conc.

CO. ENGR. F.B. 3031: 38

OF _____ F. B. _____ PG. _____

BY _____ TR. No. 26793

November 1962

P.O. Box 1054, Ferry Annex
Whittier, Calif. Phone: 691-0838



CO. ENGR. F.B. 3031: 39

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26793

DATE November, 1962

THOMSEN ENGINEERIN
16145 E. WHITTIER BL
P.O. Box 1547, Perry An
Whittier, Calif. Phone: 69

114-37A-1

W.S. 37, D-2



NOTE:
N.E.T. → Ind. Set Nail & Tag
Mrk'd. R.C.E. 8244
in Conc.

CO. ENGR. F.B. 3031: 40

OF _____ F. B. _____ Pg. _____

BY _____ TR. No. 26697

DECEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838



NOTE:
N.℄T. —o Indicates Set Nail & Tag
Marked R.C.E. 8244 in Concrete.

CO. ENGR. F.B. 3031: 41

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26697

DATE DECEMBER, 1962

THOMSEN ENGINEERING,
16145 E. WHITTIER BLV
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0



NOTE:
N.℄T. → Indicates Set Nail ℄ Tag
Marked R.C.E. 8244 in Concrete.

CO. ENGR. F.B. 3031: 42

OF _____ F. B. _____ Pg. _____

BY _____ TR. No. 26697

ECEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838



• Indicates Set Nail & Tag
of R.C.E. 8244, in Concrete

CO. ENGR. F.B. 3031: 43

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26697

DATE DECEMBER, 1962

THOMSEN ENGINEERING,
16145 E. WHITTIER BLV
P.O. Box 1547 Perry Anne
Whittier, Calif. Phone: 691-0

114-277 A-1



NOTE:
N.E.T. → Indicates Set
& Tag Marked R.C.E. 824
in Concrete.

W.J. 37, C2

CO. ENGR. F.B. 3031: 44

OF _____ F. B. _____ PG. _____

BY _____ TR. No. 26697

DECEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838

NOTE:
N.F.T. —⊙ Indicates Set Nail & Tag
Marked R.C.E. 8244 in Concrete.



CO. ENGR. F.B. 3031: 45

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 86697

DATE DECEMBER, 1962

THOMSEN ENGINEERING, I
16145 E. WHITTIER BLVD
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-08

114-277 (A-1)

W.S. 37 C R



NOTE:
N.℄T. ⊙ INDICATES Set Nail ℄ Tag
Marked R.C.E. 8244 in Concrete.

CO. ENGR. F.B. 3031: 46

OF _____ F. B. _____ PG. _____

BY _____ TR. No. 26697

DECEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838



⊙ Indicates Set Nail
Marked R.C.E. 8244,
Concrete.

CO. ENGR. F.B. 3031: 47

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26697

DATE DECEMBER, 1962

THOMSEN ENGINEERING, I
16145 E. WHITTIER BLVD
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-08



NOTE:
N.℄T. ⊸⊙ Indicates Set Nail & Tag
Marked R.C.E. 8244 in Concrete

CO. ENGR. F.B. 3031: 48

F. B. Pg.

TR. No. 26697

ECEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838



NOTE:
N.℄T. — o Indicates Set Nail & Tag
Marked R.C.E. 8244, in Concrete.

CO. ENGR. F.B. 3031: 49

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26697

DATE DECEMBER, 1962

THOMSEN ENGINEERING,
16145 E. WHITTIER BLV
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0



NOTE:
N.F.T. ⊸ Indicates Set Nail & Tag
Marked R.C.E. 8244 in Concrete

CO. ENGR. F.B. 3031: 50

OF LOFTYGROVE & GOLDEN MEADOW F B NO. 602 PAGE 18

BY ENG. SERVICE CORP. TRACT NO. 25109

1-2-63

GAN - P.C.
EDOM
DSOE



SCALE

ALL L&T TIES WITH
R.E. TAG # 5335

CO. ENGR. F.B. 3031: 51

SURVEY OF GOLDEN MEADOW & BROOKFORD F B NO. 602 PAGE 13

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25:09

DATE 1-2-63

W.S. 27 A-3



CO. ENGR. F.B. 3031:52

SURVEY OF BEECHFIELD & GOLDEN MEADOW F B NO. 602 PAGE 20

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-2-63

MORGAN - P.C.
MC BRIDE
BLEDSOE



ALL LOT TIES WITH R.S. TAG # 5335

DO NOT EXTEND NOTES THIS SIDE OF LINE

27A-5

CO. ENGR. F.B. 3031: 53

SURVEY OF GOLDEN MEADOW & TR. LINE F B NO 602 PAGE 21

SURVEY BY ENG. SERVICE CORP. TRACT NO 25109

DATE 1-2-63

MORGAN- P.C.
McBROOM
BLEDSOE



ALL L&T TIES WITH
R.E. TAG # 5335

CO. ENGR. F.B. 3031: 54.

SURVEY OF P.I. IN LOFTY GROVE DR. F B NO. 602 PAGE 22

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-2-63

MORGAN - P.C.
McBROOK
BLEDSOE



ALL L&T TIES
WITH R.B. TAG
#5335

NO SCALE

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 55

SURVEY OF MONERO & HAZELRIDGE DR. F B NO 602 PAGE 23

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-2-63

MORGAN - P.C.
MC BROOM
BLEDSOE



ALL ℄T TIES WITH
R.E. TAG # 5335

NO SCALE

W.S. 27, B-3

P.I'S IN

CO. ENGR. F.B. 3031: 56

SURVEY OF AMBERGATE & MONERO F B NO. 602 PAGE 25

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-2-63

MORGAN - P.C.
McBROOM
BLEDSOE



ALL L&T TIES WITH
P.E. TAG # 5835

NO SCALE

DO NOT EXTEND NOTES THIS SIDE OF LINE

YNS 27B3

CO. ENGR. F.B. 3031: 57

SURVEY OF BROOKFORD & AMBERGATE F B NO 602 PAGE 28

SURVEY BY ENG. SERVICE CORP. TRACT NO 25109

DATE 1-3-63

MORGAN - P.C.
MCBROOM
BLEDSOE

W527 B-3



ALL L&T TIES WITH
R.E. TAG # 5335

NO SCALE

AMBERGATE ROAD CO. ENGR. F.B. 3031:58

SURVEY OF 1ST P.I. No. OF BROOKFORD DR. F B NO. 602 PAGE [illegible]

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-2-63

MORGAN - A.C.
McBROOM -
BLEDSOE -





ALL L&T TIES WITH
B.E. TAG # 5335

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 59

SURVEY OF BROOKFORD & INDIAN ROCK F B NO. ____ PAGE 25

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-2-63



ALL LOT TIES WITH R.E. TAG # 5335

CO. ENGR. F.B. 3031: 60

SURVEY OF P.I. IN MAYCROFT DRIVE F B NO. 602 PAGE 27

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-2-63

MORGAN - P.C.
McBROOM
BLEDSOE



ALL L&T TIES WITH R.E. TAG # 5335

NO SCALE

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 61

SURVEY OF INDIAN ROCK & MAYCROFT DR F B NO 602 PAGE 29

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-3-63

MORGAN-P.C.
MC BROOM
BLEDSOE



ALL L&T TIES
WITH R.E. TAG
#5335

CO. ENGR. F.B. 3031: 62

SURVEY OF P.I. IN INDIAN PEAK RD. F B NO 602 PAGE 30

SURVEY BY ENG. SERVICE CORP. TRACT NO 25109

DATE 1-3-63

DO NOT EXTEND NOTES THIS SIDE OF LINE



ALL L&T TIES WITH R.E. TAG # 5335

CO. ENGR. F.B. 3031: 63

SURVEY OF INDIAN ROCK & LOFTYGROVE F B NO. 602 PAGE 31

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-3-63

MORGAN - P.C.
McBROOM
BLEDSOE



ALL L&T TIES WITH R.E. TAG # 5335

CO. ENGR. F.B. 3031: 64

SURVEY OF BEECHFIELD & INDIAN ROCK F B NO. 602 PAGE 32

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-3-63

MORGAN-A.C.
McBROOK
BLEDSOE



ALL L&T TIES
WITH R.E. TAG
5335

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 65

SURVEY OF P.I. IN INDIAN ROCK DRIVE F B NO. 602 PAGE 33

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-3-63

MORGAN-P.C.
McBRIDE
BLESSIDE





NO SCALE

ALL L&T TIES WITH
R.E. TAG # 5335

CO. ENGR. F.B. 3031: 66

SURVEY OF P.I. IN BEECHFIELD DR. F B NO 602 PAGE 34

SURVEY BY ENG. SERVICE CORP. TRACT NO 25109

DATE 1-3-63

MORGAN-P.C.
McBRIDE
BLEDSOE

Lot 98 Lot 99



ALL LOT TIES WITH
R.E. TAG # 5335

NO SCALE

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 67

SURVEY OF MAYCROFT & GOLDEN MEADOW F B NO. 602 PAGE 35

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-3-63

MORGAN-P.C.
McBROOM
BLEDSOE



CO.ENGR. F.B. 3031: 68

SURVEY OF INDIAN ROCK & TRACT LINE F B NO. 602 PAGE 36

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25109

DATE 1-3-63

MORGAN - R.C.
McBROOM -
BLEDSOE



DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. 3031: 69

SURVEY OF P.I.'S IN FORRESTAL DRIVE F B NO. 602 PAGE 4

SURVEY BY ENG. SERVICE CORP. TRACT NO. 26414

DATE 12-19-62

STEWART - P.C.
PETERS
MANN



CO. ENGR. F.B. 3031: 70

SURVEY OF FORRESTAL DR. & P.V. DR. SO. F B NO. 602 PAGE 5

SURVEY BY ENG. SERVICE CORP. TRACT NO. 26414

DATE 12-19-62

DO NOT EXTEND NOTES THIS SIDE OF LINE



CO. ENGR. F.B. 3031: 71

SURVEY OF P.I. AT N. TRACT LINE F B NO. 602 PAGE 6

SURVEY BY ENG. SERVICE CORP. TRACT NO 26414

DATE 12-20-62

STEWART-P.C.
PETERS
MANN



ALL L℄T TIES
WITH R.E. TAG
#5335

CO. ENGR. F.B. 3031: 72

SURVEY OF P.I.'s in Forrestal Drive F B NO. 502 PAGE 3

SURVEY BY Eng. Service Corp. TRACT NO. 264 [illegible]

DATE 12-18-62



DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 73 PERPENDICULAR

SURVEY OF NORTHERLY END OF DRIVE F B NO. 602 PAGE 2

SURVEY BY ENG. SERVICE CORP. TRACT NO. 26414

DATE 12-18-62

STEWART S.C.
PETERS
MANN



ALL LET TIES
WITH R.E. TAG
#5335

NO SCALE

CO. ENGR. F.B. 3031: 74'

SURVEY OF P.I. IN FORRESTAL DRIVE F B NO. 602 PAGE 1

SURVEY BY ENG. SERVICE CORP. TRACT NO. 26414

DATE 12-18-62

STEWART - P.C.
PETERS
MANN



DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 75

SURVEY OF P.T. HAWTHORNE 3RD F B NO. 602 PAGE 7

SURVEY BY SAN. SERVICE DEPT. TRACT NO. 25105

DATE 12-26-52

R.E. SLEEPER - P.C.
R. BILL
E. TABER



ALL TIES L℄T
WITH R.E. TAG
5335

CO. ENGR. F.B. 3031: 76

SURVEY OF ALVAREZ DR. AT HAW. BLVD. F B NO. 602 PAGE 8

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-26-62

R.E. SLEEPER - [illegible]
R. BILL
E. T. [illegible]



ALL TIES L&T
WITH R.E. TAG
5335

DO NOT EXTEND NOTES THIS SIDE OF LINE

WS-27B.5

CO. ENGR. F.B. 3031: 77

SURVEY OF P.I. IN ALVAREZ DRIVE F B NO. 602 PAGE 9

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-27-62

R. E. SLEEPER - R.C.
R. BILL
E. TREFF



ALL ℄℄T TIES WITH
R.E. TAG # 5335

CO. ENGR. F.B. 3031: 78

SURVEY OF ALVAREZ & MONERO DRIVE F B NO. 602 PAGE 10

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-27-62

R.E. SLEEPER, P.C.
R. BILL
E. TREFF



ALL L&T TIES WITH R.E. TAG 335

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 79

SURVEY OF HAW. BLVD. & TR. LINE-22200 F B NO. 252 PAGE 11

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-27-62

R.E. SLEEPER - P.C.
R. BILL
E. TREFF



ALL LET TIES WITH
R.E. TAG # 5335



CO. ENGR. F.B. 3031: 80

SURVEY OF MONERO JR. CUL-DE-SAC F B NO. 602 PAGE 12

SURVEY BY ENG. SERVICE CO. AR TRACT NO. 25106

DATE 12-27-62

R.E SLEEPER
R. BILL
E. TREEF



ALL LOT TIES WITH S.E. TIES #5335

LOT 28

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 81

SURVEY OF PLAN MONERO DRIVE F B NO. 602 PAGE 13

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-27-62

R.E. SLEEPER - P.C.
R. BALL
E. TREFF



ALL LOT TIES WITH R.E. TAG #5335

NO SCALE

CO. ENGR. F.B. 3031: 82

SURVEY OF P.I. IN MONERO DRIVE F B NO. 602 PAGE 14

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-27-62

R.E. SLEEPER - P.C.
R. BILL
E. TREFF



ALL L&T TIES WITH
B.E. TAG #5335

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 83

SURVEY OF CENTURIA & MONERO DR. F B NO 602 PAGE 15

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-27-62

R.E. SLEEPER - P.C.
R. BILL
E. TREFF



ALL L&T TIES
WITH R.B. TAG
#5335

CO. ENGR. F.B. 3031: 84

SURVEY OF P.I's in Monero Drive F B NO. 602 PAGE 16

SURVEY BY Eng. Service Corp. TRACT NO. 25106

DATE 12-27-62

R.E. SLEEPER
[illegible]
[illegible]



ALL L&T TIES
WITH R.E. TAG
#5335



DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 85

SURVEY OF CENTURIA & RIO LINDA DR. F B NO 602 PAGE 17

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-28-62

R. E. SLEEPER - P. C.
R. BILL
E. TEBBS



ALL LOT TIES
WITH R.E. TAG
5335

CO. ENGR. F.B. 3031: 86

SURVEY OF Cul-De-Sac in Rio Linda Dr. F B NO. 602 PAGE 1

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25106

DATE 12-28-62

R.E. SLEEPER - R.C.
R. BILL
E. TREFF



NO SCALE

ALL LOT TIES WITH R.E. TAG # 3355

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 87

SURVEY OF [illegible] F B NO. 502 PAGE [illegible]

SURVEY BY [illegible] TRACT NO. [illegible]

DATE 12-23-53

E.S. SLEEPER CO.
R. BILL
E. TREFF



LET TIES WITH R.E. TAG # E335

CO. ENGR. F.B. 3031: 88

SURVEY OF Rio Linda Sub-Div-54 F B NO 602 PAGE 20

SURVEY BY Eng. Service Corp. TRACT NO. 2506

DATE 12-23-62

DO NOT EXTEND NOTES THIS SIDE OF LINE



ALL LOT TIES
WITH R.S. TIES
#5335

NO SCALE

CO. ENGR. F.B. 3031: 89

SURVEY OF VILLA ROSA [illegible] F B NO. 602 PAGE 23

SURVEY BY ENG. SERVICE CORP. TRACT NO. 25105

DATE 12-28-62

R.E. SLEEPER - F.C.
R. BILL
E. TREFF



ALL L&T TIES WITH
R.E. TAG #5335

NO SCALE

CO. ENGR. F.B. 3031: 90

SURVEY OF [illegible] F B NO. [illegible] PAGE [illegible]

SURVEY BY ENG. SERVICE [illegible] TRACT NO. [illegible]

DATE 12-28-62

[illegible]



ALL L&T TIES WITH
R.E. TAG # 5335

DO NOT EXTEND NOTES THIS SIDE OF LINE

CO. ENGR. F.B. 3031: 91

SURVEY OF P.I. IN VILLA ROSA DRIVE F B NO 602 PAGE 22

SURVEY BY ENG. SERVICE CORP. TRACT NO 25106

DATE 12-28-62

P.E. SLEEPER - RC
R. BILL
E. TREFF



ALL L&T TIES WITH R.E. TAG # 5335

NO SCALE

CO. ENGR. F.B. 3031: 92

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26307

DATE NOVEMBER, 1962



THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838

NOTE:
N.F.T.—○ Indicates Set Nail & Tag Marked R.C.E. 8244 in Conc.

CO. ENGR. F.B. 3031: 93

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26307

DATE NOVEMBER, 1962

114-277 A-1



NOTE:

N ℄ T —o Indicates Set Nail & Tag
Marked R.C.E. 8244
in Conc. Blk. Wall

CO. ENGR. F.B. 3031: 94

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838



NOTE:
N. & T. — Indicate Set Nail & Tag Marked R.C.E. 8244 in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 95

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838



NOTE:
N.&T. → Indicates Set Nail & Tag Marked R.C.E. 8244 in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 96

SURVEY OF _____ F. B. _____ Pg. _____

SURVEY BY _____ TR. No. 26307

DATE NOVEMBER, 1962

1.76
36.82
38.58

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838

NOTE.
N.f.T.= Indicates Set Nail & Tag Marked R.C.E. 8244 in Conc.
All Ties Tangent

CO. ENGR. F.B. 3031: 97

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838

114-277 A-1

W.S. 37 C-2



NOTE:
N.℄T.= Indicate Set Nail & Tag
Marked R.C.E. 8244. in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 98

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26307

DATE NOVEMBER, 1962



THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838

NOTE:
N.&T.-o Indicates Set Nail & Tag Marked B.C.E. 8244. in Conc.

CO. ENGR. F.B. 3031: 99

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838

W.S. 37 C-2



Note:
N℄T.-o Indicates Set Nail & Tag
Marked R.C.E. 8244. in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 100

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26907

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838



NOTE:
N. ℄ T. ⊙ Indicates Set Nail & Tag
Marked R.C.E. 8244 in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 101

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0638



NOTE:
℄ T.+0 Indicates Set Nail & Tag
Marked R.C.E. 8244 in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 102

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. No. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838

11-27-A1



NOTE:
N.℄T.—○ Indicates Set Nail & Tag Marked R.C.E. 8244 in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 103

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547, Perry Annex
Whittier, Calif. Phone: 691-0838

W.S. 37 C-2



NOTE:
N. & T. ⊙ Indicates Set Nail & Tag
Marked R.C.E. 8244 in Conc.

All ties are tangent

CO. ENGR. F.B. 3031: 10

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY _____ TR. NO. 26307

DATE NOVEMBER, 1962

THOMSEN ENGINEERING, INC.
16145 E. WHITTIER BLVD.
P.O. Box 1547 Perry Annex
Whittier, Calif. Phone: 691-0838



NOTE:
N.E.T. Indicates Set Nail & Tag
Marked R.C.E. 8244 in Conc.

All ties are tangent

END