Notes Ck'd by	Survey of	F. B. 4024 PG.
Map No.	JN Tape Std °F	
Office Work	Surveyed by	
Checked	Notes Date	
Date	Indexed	

TRACT	PAGE	FIRM
31057	5-19	Jennings Engr. Co.
30629	20-31	Ervin Engr.
27246	32-34	Ervin Engr.
31255	35	Loren C. Phillips
29074	36	Loren C. Phillips
30017	37-41	James W. Nachazel
.M. [illegible]495	42	Lowell W. Felt
[illegible]43	43	E.L. Pearson & Assoc.
.M. [illegible]774	44	Thomsen Engr. Inc.
.M. [illegible]711	45-46	Edward L. Bolden
28756	47-49	Hicks & Hartwock
29778	50-51	R.V. Pearsall
27798	52-54	D.D. Greek
29445	55-56	Engr. Service Corp.
.M. 2154	57-A,B	Spindler Engr. Corp.
.M. 2158	58-A,B	" " "
30423	59	Spindler Engr. Corp.
27722	60-65	Egil Hopen
31350	66	McIntire & Quiros
27568	67-68	Sikand Engr. Assoc.
25920	69-75	Richard S. Angvire
.M. 2878	76	Edward L. Bolden Jr.
.M. 3161	77	R. Widmann
.M. 3159	78	R. Widmann

Microfilmed Dec. '84

over

F. B. 4024 PG. _____

TRACT	PAGE	FIRM
28659	79-92	Ervin Engr.
31438	93	Lanco Engr.
27970	94-96	McIntire & Quiros
29644	97	Engr. Service Corp.
29873	98	Wesley R. Lind
31398	99	Toups Eng. Inc.
P.M. 3617	100-101	Anacal Engr. Co.
P.M. 3766	102	Sikand Engr. Assoc.
30463	103-108	Richard S. Angvire
30469	109-114	Richard S. Angvire
28478	115-116	J.H. Edwards Co.
P.M. 3544	117	Raymond Scott Engr. Co
29834	118-121	Harold Roach
30249	122-124	K. Schorr
27605	125-127	McIntire & Quiros Inc.
29123	128-130	Kemmerer Engr. Co.
29506	131-134	Kemmerer Engr. Co.
30739	135-141	Enrique Acevedo
P.M. 3337	142	Vic Case
28924	143	Loren C. Phillips
31394	144-145	Eng. Service Corp.
27702	146-148	Richard S. Angvire
29855	149-156	Verpet Engr.
29272	157-161	Highland Engr.
29749	162	Ronald W. Spindler
29747	163-165	Ronald W. Spindler

Co. Eng. F.B. 4024: 5

SURVEY OF CENTER LINES F. B. _____ PG. 1

SURVEY BY JENNINGS ENGINEERING CO. TR. No. 31057

DATE FEB. 2, 1973

GORDON J. JENNINGS R.C.E. 7858

W5 N0A-5

SO. CALIF. BLUE PRINT CO.

GINGHAM AVENUE: FR. AVE. J-3 TO 230' S/O AVE. J-5

AVENUE J-3: FR. GINGHAM AVENUE TO RAYSACK AVENUE

AVENUE J-4: FR. GINGHAM AVENUE TO 5TH STREET EAST

RAYSACK AVENUE: FR. AVENUE J-4 TO 639' SOUT

5TH STREET EAST: FR. AVENUE J-4 TO 618' SOUT

CENTER LINE TIES

SURVEYOR: C. SNOOK
CHAINMAN: N. LARSON
CHAINMAN: K. PORTER

DISTANCES SHOWN AS MEASURED ARE CORRECTED TO 68° F.

Co. Eng. F.B. 4024: 6

SURVEY OF _____ F. B. _____ Pg. 2

SURVEY BY JENNING ENGINEERING CO. TR. No. 31057

DATE FEB 2, 1973

G. J. JENNINGS R.C.E. 7858

226

NS 70 A-5



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 7

SURVEY OF _____ F. B. _____ Pg. 3

SURVEY BY Jennings Engineering Co. TR. No. 31057

DATE FEB 2, 1973

GORDON J. JENNINGS RCE 7858

226

5 76A-5



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 8

SURVEY OF _____ F. B. _____ Pg. 4

SURVEY BY Jennings Engineering Co.,

TR. No. 41057

DATE FEB 2, 1973

GORDON J. JENNINGS R.C.E. 7858



SO. CALIF. BLUE PRINT CO. — F-1638

Co. Eng. F.B. 4024: 9

SURVEY OF _____ F. B. _____ PG. 5

SURVEY BY Jennings Engineering Co. TR. NO. 31057

DATE FEB 2, 1973

GORDON J. JENNINGS RCE 7858



704-5

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 10

SURVEY OF _____ F. B. _____ PG. 6

SURVEY BY JENNINGS ENGINEERING CO. TR. NO. 31057

DATE FEB 2, 1973

G. J. JENNING R.C.E. 7858



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 11

SURVEY OF _____ F. B. _____ PG. 7

SURVEY BY JENNINGS ENGINEERING Co TR. No. 31057

DATE FEB 2, 1973

G. J. JENNINGS R.C.E. 7858



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 12

SURVEY OF _____ F. B. _____ PG. 8

SURVEY BY Jennings Engineering Co. TR. NO. 31057

DATE FEB 2, 1973

GORDON J. JENNINGS RCE 7858

70A-5



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 13

SURVEY OF _____ F. B. _____ PG. 9

SURVEY BY Jennings Engineering Co. TR. No. 31057

DATE FEB. 2, 1973

GORDON J. JENNINGS RCE 7858

70A.5



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 14

SURVEY OF _____ F. B. _____ PG. 10

SURVEY BY Jennings Engineering Co. TR. No. 31057

DATE FEB 2, 1973

GORDON J. JENNINGS RCE 7858



70A-5

SO. CALIF. BLUE PRINT CO.

Co. Eng.F.B. 4024: 15

SURVEY OF _____ F. B. _____ PG. 11

SURVEY BY JENNINGS ENGINEERING CO. TR. No. 31057

DATE FEB 2, 1973

G.J. JENNINGS R.C.E. 7858



70 A-5

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 16

SURVEY OF _____ F. B. _____ PG. 12

SURVEY BY JENNINGS ENGINEERING CO. TR. NO. 31057

DATE FEB 8, 1973.

G. J. JENNINGS R.C.E. 7858

70 A-5

SO. CALIF. BLUE PRINT CO.



Co. Eng. F.B. 4024: 17

SURVEY OF

F. B. Pg. 13

SURVEY BY JENNINGS ENGINEERING CO.

TR. No. 31057

DATE FEB. 2, 1973

G. J. JENNINGS R.C.E. 7858

70 A-5



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 18

SURVEY OF _____ F. B. _____ PG. 14

SURVEY BY Jennings Engineering Co. TR. NO. 31057

DATE FEB 2, 1973

GORDON J. JENNINGS RCE 7858

226

70 A-5



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 19

SURVEY OF _____ F. B. _____ PG. 15

SURVEY BY JENNINGS ENGINEERING CO. TR. No. 31057

DATE MAR. 21, 1973

G. J. JENNINGS R.C.E. 7858



226

W 570 A-3

ED. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 20

SURVEY OF ℄ TIES F. B. 2 PG. 209

SURVEY BY ERVIN ENGINEERING TR. NO. 30629

DATE FEB 1973

FRED F. ERVIN RCE 11932

All 2" IPs shown as set on this Tract are set 6" Below the surface of the Ground.



(13)

SO. CALIF. EDISON CO. 049-337, A-1

Co. Eng. F.B. 4024: 21

SURVEY OF ¢ TIES F. B. 2 PG. 210

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB. 1973

FRED F. ERVIN RCE 11932



099-357 A-1

(15)

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 22

SURVEY OF ℄ TIES F. B. 2 Pg. 211

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB UNLESS OTHERWISE NOTED.



799-337 4-1

SO. CALIF. PRINT CO.

Co. Eng. F.B. 4024: 23

SURVEY OF ℄ TIES F. B. 2 PG. 212

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB UNLESS OTHERWISE NOTED



SO. CALIF. BLUE PRINT CO.

099-337 A-1

Co. Eng. F.B. 4024: 24

SURVEY OF ℄ TIES F. B. 2 PG. 213

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB. 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB UNLESS OTHERWISE NOTED



SO. CALIF. BLUE PRINT CO.

099.337 A-1 (13)

Co. Eng. F.B. 4024; 25

SURVEY OF ℄ TIES F. B. 2 PG. 214

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB



099-537 A-1

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 26

SURVEY OF ℄ TIES F. B. 2 Pg. 215

SURVEY BY ERUIN ENGINEERING TR. No. 30629

DATE FEB 1973

FRED F. ERUIN RCE 11932



SO. CALIF. BLUE PRINT CO.

099.337,A1

Co. Eng. F.B. 4024: 27

SURVEY OF ℄ TIES F. B. 2 PG. 216

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB. 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L & T IN CURB



099-337
A-1

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 28

SURVEY OF ℄ TIES F. B. 2 Pg. 217

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB 1973

FRED F. ERVIN RCE 11932



099-33341

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 29

SURVEY OF ℄ TIES F. B. 2 PG. 218

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB. 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB



OM 337, 4-1

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 30

SURVEY OF ℄ TIES F. B. 2 PG. 219

SURVEY BY ERVIN ENGINEERING TR. No. 30629

DATE FEB 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB

(13)

219-337 A-1



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 31

(13)

099-537 A-1

SURVEY OF: ℄ TIES — F. B. 2 PG. 220

SURVEY BY: ERVIN ENGINEERING — TR. NO. 30629

DATE: FEB 1973

FRED F. ERWIN RCE 1193.
NOTE: ALL TIES ARE L&T IN CURB



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 32

SURVEY OF ℄ TIES F. B. 2 Pg. 221

SURVEY BY ERVIN ENGINEERING TR. No. 27246

DATE FEB 1973

FRED F. ERVIN RCE 11932

2" IPs. shown as set are set 6" below the surface of the ground.



60

09A337A-2

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 33

SURVEY OF: ℄ TIES — F. B. 2 PG. 222

SURVEY BY: ERVIN ENGINEERING — TR. NO. 27246

DATE: FEB. 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB UNLESS OTHERWISE NOTED



60

099.337 A.2

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 34

SURVEY OF: ℄ TIES — F. B. — PG. 223

SURVEY BY: ERVIN ENGINEERING — TR. No. 27246

DATE: FEB 1973

FRED F. ERVIN RCE 11932

NOTE: ALL TIES ARE L & T IN CURB



G 09-337 #2

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 35

SURVEY OF ℄ TIES FOOTHILL BLUD. F. B. _____ PG. _____

SURVEY BY LOREN C. PHILLIPS L.S. #3173 TR. No. 31255

DATE MARCH 10, 1973



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 36

SURVEY OF ℄ TIES FOURTH AVE. F. B. _____ PG. _____

SURVEY BY LOREN C. PHILLIPS L.S. 3173 TR. No. 29074

DATE MARCH 21, 1973



60

SO. CALIF. BLUE PRINT CO. 5545 C-5

Co. Eng. F.B. 4024: 37

SURVEY OF CENTERLINE TIE-NOTES F. B. 6 PG. 13

SURVEY BY JAMES W. NACHAZEL R.C.E. 15823 TR. No. 30017

DATE DEC. 27, 1972

NOTE! ALL TIE MONUMENTS ARE CONCRETE NAILS & TAGS SHOT IN TOP OF CURB, EXCEPT AS NOTED



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 38

F. B. 6 PG: 14 SURVEY OF CENTERLINE TIE-NOTES

TR. No. 30017 SURVEY BY JAMES W. NAGHAZEL R.C.E. 15823

DATE DEC. 27, 1972

NOTE! ALL TIE MONUMENTS ARE CONCRETE NAILS AND TAGS SHOT IN TOP OF CURB.



Co. Eng. F.B. 4024: 139

SURVEY OF CENTERLINE TIE-NOTES F. B. 6 PG. 15

SURVEY BY JAMES W. NACHAZEL R.C.E. 15823 TR. No. 30017

DATE DEC. 27, 1972

NOTE! ALL TIE MONUMENTS ARE CONCRETE NAILS & TAGS SHOT IN TOP OF CURB



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 40

F. B. 6 PG. 16 SURVEY OF CENTERLINE - TIE NOTES

TR. No. 30017 SURVEY BY JAMES W. NACHAZEL R.C.E. 15828

DATE DEC. 27, 1972

NOTE! ALL TIE MONUMENTS ARE CONCRETE NAILS & TAGS SHOT IN TOP OF CURB.



Co. Eng. F.B. 4024: 41

SURVEY OF CENTERLINE - TIE-NOTES F. B. 6 PG. 17

SURVEY BY JAMES W. NACHAZEL, R.C.E. 15823 TR. NO. 30017

DATE DEC. 27, 1972

NOTE! ALL TIE MONUMENTS ARE CONCRETE NAILS & TAGS SHOT IN TOP OF CURB.



71 D-5 69

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 42

SURVEY OF CENTERLINE TIE NOTES F B NO. _____ PAGE _____

SURVEY BY LOWELL W. FELT TRACT NO. PM 3495

DATE 4-26-73 RCE 8732



59

2566 A-9

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 4

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Eng. F.B. 4024: 43

SURVEY OF ℄ Ties F. B. ____ PG. ____

SURVEY BY E.L. PEARSON & ASSOC. - R.C.E. 9783 TR. No. 29343

DATE 5-9-73

49

527 B-2

SO. CALIF. BLUE PRINT



Co. Eng. F.B. 4024: 44

SURVEY OF ℄ TIES F B NO. PAGE 1

SURVEY BY THOMSEN ENGINEERING, INC. TRACT NO. P.M. 2774

HANS C. THOMSEN RCE 8244

DATE APRIL 1973



SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

31

WT 37 E-4

Co. Eng. F.B. 4024: 45

SURVEY OF Peperidge Drive

F. B. ____ PG. ____

SURVEY BY Edward L. Bolden, Jr. R.C.E. 10533

Parcel Map 3711

TR. NO. ____

DATE May 14, 1973



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 46

~~PRB.~~ ~~PG.~~ Parcel Map SURVEY OF Peperidge Drive

~~Parcel Map No.~~ 3711 SURVEY BY Edward L. Bolden, Jr., R.C.E. 10533

TR. No.

DATE May 14, 1973

249-117, B-3



Tract No. 28756 December 1, 1972 Page 1 of 3

Survey By: Hicks & HARTWICK
Engrs. ~ Surveyors James N. Hicks R.C.E 859



Co. Eng. F.B. 4024: 48

Tract No. 28756 December 1, 1972 Page 2 of 3

Survey By: Hicks & Hartwick
Engrs. ~ Surveyors

James N. Hicks R.C.E. 8591



J583 D-4 (5)

Tract No 28756 December 1, 1972 Page 3 of 3

Survey By: Hicks & Hartwick
Engrs. ~ Surveyors

James N. Hicks R.C.E 8591



Co. Eng. F.B. 4024: 50

SURVEY OF ℄ 61ST PLACE F B NO. PAGE

SURVEY BY R.V. PEARSALL LS 1339 TRACT NO. 29778

DATE 4/10/73



(54) WS 31 B-6

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Eng. F.B. 4024: 51

SURVEY OF ℄ 62ND PLACE F B NO. PAGE

SURVEY BY R.V. PEARSALL LS 1339 TRACT NO. 29778

DATE 4/10/73



DO NOT EXTEND NOTES THIS SIDE OF LINE

(54) 31 B-6

Co. Eng. F.B. 4024: 52

SURVEY OF ℄ TIES F B NO. PAGE

SURVEY BY D.D. GREEK, R.C.E. 12971 TRACT NO. 27798

DATE 3-19-73

DO NOT EXTEND NOTES THIS SIDE OF LINE



Co. Eng. F.B. 4024: 53

SURVEY OF ℄ TIES F B NO. PAGE

SURVEY BY D.D. GREEK, R.C.E. 12971 TRACT NO. 27798

DATE 3-19-73



SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

6933B-6

Co. Eng. F.B. 4024: 54

SURVEY OF ℄ TIES F B NO. ____ PAGE ____

SURVEY BY D.D. GREEK, RCE. 12971 TRACT NO. 27798

DATE 3-19-73

DO NOT EXTEND NOTES THIS SIDE OF LINE

33 B-5 (40)



Co. Eng. F.B. 4024: 55

SURVEY OF JOHNSON ROAD F B NO. ____ PAGE 1

SURVEY BY ENGINEERING SERVICE CORP. TRACT NO. 29445

DATE APRIL 1973

J.K. NEWVILLE
R.C.E. 13095



SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 41

DO NOT EXTEND NOTES THIS SIDE OF LINE

(12) C-5

WS 72

Co. Eng. F.B. 4024: 56

SURVEY OF JOHNSON ROAD F B NO. PAGE 2

SURVEY BY ENGINEERING SERVICE CORP. TRACT NO. 29445

DATE APRIL 1973

J. K. NEWVILLE
R.C.E. 13095

W572C-5 (12)

DO NOT EXTEND NOTES THIS SIDE OF LINE



Co. Eng. F.B. 40241-7A

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY SPINDLER ENGR. CORP.

~~TR. No.~~ PM. 2154

DATE MARCH 1973

Ronald W. Spindler RCE 13194

76

B-2

26 4-11-73

SO. CALIF. BLUE PRINT CO.



1

Co. Eng. F.B. 4024: 57B

F. B. _____ PG. _____ SURVEY OF _____

TR. No. P.M. 2154 SURVEY BY SPINOLER ENGR. CORP.

DATE MARCH 1973

Ronald W. Spindler RCE 13194

264-117 B-2 (76)



Co. Eng. F.B. 4024:58A

SURVEY OF _____ F. B. _____ PG. 1 of 2

SURVEY BY SPINDLER ENGR. CORP.

~~TR.~~ No. P.M. 2158

DATE MARCH 1973

Ronald W. Spindler, RCE 13194



264/17 B-2 (77)

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 58 B

F. B. _____ PG. 2 of 2 SURVEY OF _____

TR. No. P.M. 2158 SURVEY BY SPINDLER ENGR. CORP.

DATE MARCH 1973

Ronald W. Spindler, RCE 13194

SCALE
1" = 40'

N



264-117B

F. B. _____ PG. 1 of 1 SURVEY OF _____

TR. NO. 30423 SURVEY BY SPINDLER ENGR. CORP.

DATE MARCH 1973

Ronald W. Spindler
RCE 13194

264.117 B-1

73



Co. Eng. F.B. 4024: 60

SURVEY OF CENTERLINE TIES F. B. Pg. 1

SURVEY BY EGIL HOPEN, L.S. 2600 TR. No. 27722

DATE FEB. 27, 1973



(49)

099-297 B-1

SO. CALIF. BLUE PRINT CO.

SURVEY OF CENTERLINE TIES F. B. Pg. 2

SURVEY BY EGIL HOPEN, L.S. 2600 TR. No. 27722

DATE FEB. 23, 1973



SEE PAGE 1

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 62

SURVEY OF CENTERLINE TIES F. B. Pg. 3

SURVEY BY EGIL HOPEN, L.S. 2600 TR. No. 27722

DATE FEB. 27, 1973



SO. CALIF. BLUE PRINT CO.

099-297, B-1

Co. Eng. F.B. 4024: 63

SURVEY OF CENTERLINE TIES F. B. Pg. 4

SURVEY BY EGIL HOPEN, L.S. 2600 TR. No. 27722

DATE FEB. 23, 1973



SEE PAGE 2



SO. CALIF. BLUE PRINT CO.

099 287 R1

Co. Eng. F.B. 4024: 64

SURVEY OF CENTERLINE TIES

SURVEY BY EGIL HOPEN, L.S. 2600

DATE FEB. 23, 1973

F. B. PG. 5

TR. No. 27722

029-297, B-1



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 65

SURVEY OF CENTERLINE TIES F. B. Pg. 6

SURVEY BY EGIL HOPEN, L.S.2600 TR. No. 27722

DATE Feb. 27, 1973

(49)

09-297 P-1



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 66

SURVEY OF TR. No. 31350 & TIES F. B. _____ PG. 2

SURVEY BY Mc Intire & Quiros Inc TR. No. 31350

DATE May 1973

Fernando Quiros R.C.E. 8583



232
WS28 A-3

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 67

SURVEY OF ℄ Ties F. B. ____ PG. 1

SURVEY BY Sikand Engr Assoc TR. No. 27568

DATE 5-24-73

Ronald R. Hom RCE 16913



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 68

F. B. _____ PG. 2 SURVEY OF ℄ Ties - Tract No. 27568

TR. No. 27568 SURVEY BY Sikand Engr. Assoc.

DATE 5-24-73

Ronald R. Horn
RCE 16913



C49-117 A-2

Co. Eng. F.B. 4024: 69

SURVEY OF _____ F B NO. _____ PAGE 1

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 25920

DATE 4-30-73 R.C.E. 9284



SURVEYORS SERVICE COMPANY, LOS ANGELES - STOCK NO. 411
DO NOT EXTEND NOTES THIS SIDE OF LINE

9 4567 C-6

Co. Eng. F.B. 4024: 70

F B NO. _____ PAGE 2

TRACT No. 25920 APRIL 30, 1973

SURVEY BY RICHARD S. ANGVIRE, R.C.E. 9284

W.S. 67, C-6

(10)



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY - LOS ANGELES - STOCK NO. 411

Co. Eng. F.B. 4024: 71

SURVEY OF _____ F B NO. _____ PAGE 3

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 25920

DATE 4-30-73 R.C.E. 9284

DO NOT EXTEND NOTES THIS SIDE OF LINE



Co. Eng. F.B. 4024: 72

F B NO. _____ PAGE 4

TRACT No. 25920 APRIL 30, 1973

SURVEY BY RICHARD S. ANGVIRE, R.C.E. 9284



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMP. LOS ANGELES - STOCK NO. 411

Co. Eng. F.B. 4024: 73

SURVEY OF _____ F.B. NO. _____ PAGE 5

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 25920

DATE 4-30-73 R.C.E. 9284



(14) MS.67 C-6

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Eng. F.B. 4024: 74

F B NO. _____ PAGE 6

TRACT NO. 25920 APRIL 30, 1973

SURVEY BY RICHARD S. ANGVIRE, R.C.E. 9284

(16) W.S. 67, C-2



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY - LOS ANGELES - STOCK NO. 411

Co. Eng. F.B. 4024: 75

SURVEY OF _____ F B NO. _____ PAGE 7

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 25920

DATE 4-30-73 R.C.E. 9284



SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 111

DO NOT EXTEND NOTES THIS SIDE OF LINE

(18)

US 67, C6

Co. Eng. F.B. 4024: 76

SURVEY OF P.M. 2878 F. B. Pg.

SURVEY BY Edward L. Bolden, Jr., R.C.E. 10533 TR. NO. P.M. 2878

DATE 5/25/73



244-117 A.3

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 77

TRACT NO. P.M. Nº 3161 DATE 5·22·73 PAGE 1 OF 1

SURVEY ENGINEER R. WIDMANN R.C.E. 6246



WS34B5

Co. Eng. F.B. 4024: 78

TRACT NO. PM N°. 3159 DATE 5·22·73 PAGE 1 OF 1

SURVEY ENGINEER R. WIDMANN R.C.E. 6246

53

W.S. 34 B-5



Co. Eng.F.B. 4024: 79

SURVEY OF: & TIES

F. B. 2 PG. 230

SURVEY BY: ERVIN ENGINEERING

TR. No. 28655

DATE: FEB. 1973

FRED ERVIN RCE 11932



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 80

SURVEY OF ℄ TIES F. B. 2 Pg. 231

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB.



129-337/A-1

SO. CALIF. BLUE PRINT CO.

UV548 B-4

Co. Eng. F.B. 4024: 81

SURVEY OF ℄ TIES

F. B. 2 PG. 232

SURVEY BY ERVIN ENGINEERING

TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T. IN CURB.



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 82

SURVEY OF ℄ TIES F. B. 2 PG. 233

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB.



144-337 A-3

129-337 A-1

W548, B-9

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 83

SURVEY OF: ℄ TIES — F. B. 2 PG. 234

SURVEY BY: ERVIN ENGINEERING — TR. NO. 28655

DATE: FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T. IN CURB.



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 84

SURVEY OF ℄ TIES F. B. 2 PG. 235

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB.



144-537, A-3

WS48 B9

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 85

SURVEY OF ℄ TIES F. B. 2 PG. 236

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T. IN CURB.



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 86

SURVEY OF ℄ TIES F. B. 2 PG. 237

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973



144-337, A-3

WS48B-4

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 87

SURVEY OF ℄ TIES F. B. 2 PG. 238

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB.



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 88

SURVEY OF ℄ TIES F. B. 2 PG. 239

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB.



144-3 St A-3

WS48B-4

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 89

SURVEY OF ℄ TIES F. B. 2 PG. 240

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T. IN CURB.



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 90

SURVEY OF ℄ TIES F. B. 2 PG. 241

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE LET IN CURB.



144-3374-3

W.S. 48, B-4

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 91

SURVEY OF ℄ TIES F. B. 2 PG. 242

SURVEY BY ERVIN ENGINEERING TR. No. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB.



SO. CALIF. BLUE PRINT CO.

X

Co. Eng. F.B. 4024: 92

SURVEY OF ℄ TIES F. B. 2 PG. 243

SURVEY BY ERVIN ENGINEERING TR. NO. 28655

DATE FEB. 1973

FRED ERVIN RCE 11932

NOTE: ALL TIES ARE L&T IN CURB.



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 93

SURVEY OF CENTER LINE TIES F. B. ____ PG. ____

SURVEY BY LANCO ENGINEERING TR. NO. 31438

DATE JUNE, 1973

LANCO: C.M. LEONARD, R.C.E. 13167



60

WS 28 B-2

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 94

SURVEY OF _____ F. B. _____ PG. 1

SURVEY BY Mc Intire & Quiros TR. No. 27970

DATE June 1973

Ray E. Widmer RCE 11758

23

B-2

159037

SO. CALIF. BLUE PRINT CO.



Co. Eng. F.B. 4024: 95

SURVEY OF _____ F. B. _____ PG. 2

SURVEY BY McIntire & Quiros TR. NO. 27970

DATE June 1973

Ray E. Widmer RCE 11758



SO. CALIF. BLUE PRINT CO.

(2)

152037 B.2

Co. Eng. F.B. 4024: 96

SURVEY OF _____ F. B. _____ PG. 3

SURVEY BY McIntire & Quiros

TR. No. 27970

DATE June 1973

Ray E. Widmer RCE 11758



(23) 4-2

159-037

SO. CALIF. BLUE PRINT CO.

Pg. 2 No

See

Co. Eng. F.B. 4024: 97

SURVEY OF 231 ST STREET F B NO. PAGE

SURVEY BY ENGINEERING SERVICE CORP. TRACT NO. 29644

DATE MAR. 1973

J. K. NEWVILLE
R. C. E. 13095

29

W527 E1



SURVEYORS SERVICE COMPANY, TA MESA - STOCK NO. 411
DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Eng. F.B. 4024: 98

SURVEY OF ℄ TIES PAGE 1 OF 1

SURVEY BY WESLEY R. LIND RCE 16362 TR. No. 29873

DATE April 24, 1973

W.S. 45 (18)



SCALE: 1"=50'

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 99

TRACT NO. 31398 DATE 6-29-73 PAGE

ENGINEER TERRANCE K. BARRY R.C.E. 14010

SURVEY BY TOUPS ENGINEERING, INC.

(22)
1570 A-4



Co. Engr. F.B. 4024: 100

PARCEL MAP Nº 3617, Date 6-73, PAGE 1 of 2

C. J. Queyrel L.S. 2988

By ANACAL ENGINEERING CO.



W.S.37. ⑨ C-2

PARCEL MAP Nº 3617 Date 6-73 PAGE 2 of 2

C. J. Queyrel L.S. 2988

By ANACAL ENGINEERING CO.

414-277 A-1



Co. Engr.F.B. 4024: 102

SURVEY OF ℄ Ties – PM No. 3766 F. B. ____ PG. 1

SURVEY BY Sikond Engr. Assoc. PM ~~TR.~~ No. 3766

DATE 6-12-73 G.S. Sikond RCE 9553

PM 46-82,83

(141)

264-097 B.2



SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 103

SURVEY OF _____ F B NO. _____ PAGE 1

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 30463

DATE 5-24-73 RCE 9284



22

73D-2

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Engr. F.B. 4024: 104

F B NO. PAGE 2

SURVEY BY RICHARD S. ANGVIRE, RCE 9284
TRACT No. 30463 5-24-73

All 2X2s are tagged RCE 9284



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

73D-2

Co. Engr. F.B. 4024: 105

SURVEY OF _____ F B NO. _____ PAGE 3

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 30463

DATE 5-24-73 RCE 9284



73 D-2

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Engr. F.B. 4024: 106

F B NO. ____ PAGE 4

SURVEY BY RICHARD S. ANGVIRE, RCE 9284
TRACT No. 30463 5-24-73



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

73 D-2

Co. Engr. F.B. 4024: 107.

SURVEY OF _____ F B NO. _____ PAGE 5

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 30463

DATE 5-24-73 RCE 9284

73-D-2



All 2"x2" stakes are tagged RCE 9284

SURVEYORS SERVICE COMPANY A MESA - STOCK NO. 411
DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Engr. F.B. 4024: 108

F B NO. ____ PAGE 6

SURVEY BY RICHARD S. ANGVIRE, RCE 9284
TRACT No. 30463 5-24-73



All 2"x2" stakes are tagged RCE 9284

DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

22 D-2

WS 73

Co. Engr. F.B. 4024: 109

SURVEY OF _____ F B NO _____ PAGE 1

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 30469

DATE 5-24-73 RCE 9284



SURVEYORS SERVICE COMPANY COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

5/8/73 (2) D-2

Co. Engr.F.B. 4024: 110

F B NO. PAGE 2

SURVEY BY RICHARD S. ANGVIRE, RCE 9284
TRACT NO. 30469 5-24-73

73 D-2



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

Co. Engr. F.B. 4024: 111

SURVEY OF _____ F B NO _____ PAGE 3

SURVEY BY RICHARD S. ANGVIRE TRACT NO 30469

DATE 5-24-73

73 p.2



SURVEYORS SERVICE COMPANY, TA MESA - STOCK NO. 411
DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Engr. F.B. 4024: 112

F B NO. _____ PAGE 4

SURVEY BY RICHARD S. ANGVIRE, RCE 9284
TRACT No. 30469 5-24-73

13D-2



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

Co. Engr. F.B. 4024: 113

SURVEY OF _____ F B NO. _____ PAGE 5

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 30469

DATE 5-24-73 RCE 9284



SURVEYORS SERVICE COMPANY, TA MESA - STOCK NO. 411
DO NOT EXTEND NOTES THIS SIDE OF LINE

73D2

Co. Engr. F.B. 4024: 114

F B NO. 1 PAGE 6

SURVEY BY RICHARD S. ANGVIRE, RCE 9284
TRACT No. 30469 5-24-73

W.S. 73 D 2 (12)



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

Co. Engr. F.B. 4024: 115 .

SURVEY OF CENTERLINE TIES F B NO. PAGE 1

SURVEY BY J. H. EDWARDS CO. TRACT NO. 28478

DATE 5-21-73

ENGINEER: J. H. EDWARDS
R.C.E. 11302



SURVEYORS SERVICE COMPANY STA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

1538 R

Co. Engr. F.B. 4024: 116

SURVEY OF CENTERLINE TIES F B NO. _____ PAGE 2

SURVEY BY J.H. EDWARDS CO. TRACT NO. 28478

DATE 5-18-73

ENGINEER: J.H. EDWARDS R.C.E. 11302



A1536 D.2

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Engr. F.B. 4024: 117

SURVEY OF _____ F. B. _____ PG. _____

SURVEY BY RAYMOND SCOTT ENGINEERING CO. P.M. No. 3544

DATE JUNE 30, 1973

RAYMOND J. SCOTT R.C.E. 14356

W.S. 324-237 A-3



SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 118

SURVEY OF _____ F. B. _____ PG. 1 of 4

SURVEY BY HAROLD ROACH, R.C.E. No. 5463 TR. No. 29834

DATE MAY 11, 1973



W.S. 144-297 c-2

W.S. 47 C-3

SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 119

SURVEY OF _____ F. B. _____ PG. 2 of.

SURVEY BY HAROLD ROACH, R.C.E. No. 5463 TR. No. 29834

DATE MAY 11, 1973



W.S. 4763

W.S. 144-297 C-2

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 120

SURVEY OF _____ F. B. _____ PG. 3 of 4

SURVEY BY Harold Roach R.C.E No. 5463 TR. No. 29834

DATE May 11, 1973



W.S. 144-299 C-2

47 C 3

SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 121

SURVEY OF _____ F. B. _____ PG. 4 of 4

SURVEY BY Harold Roach, R.C.E. No. 5463 TR. No. 29834

DATE May 11, 1973



W.S. 144-297 C-2

47C3

SO. CALIF. BLUE PRINT CO.

Co. Engr.F.B. 4024: 122

SURVEY OF 8 TIES F. B. ____ PG. 1

SURVEY BY K. SCHOOP, RCE 12955 TR. No. 30249

DATE 5-11-73

NOTE: ALL S&T ARE TAGGED RCE 12955 UNLESS OTHERWISE NOTED.



NOTE: All Ties are L&T Set in top of curb unless otherwise noted.

(151) W571 D-5

SO. CALIF. BLUE PRINT CO. B8276

Co. Engr. F.B. 4024: 123

F. B. _____ PG. 2 SURVEY OF E TIES

TR. No. 30245 SURVEY BY K SCHARR RCE 12955

DATE 5-11-73

(15)

W.S. 71 D.S.



Co. Engr. F.B. 4024: 124

SURVEY OF 2 TIES F. B. Pg. 3

SURVEY BY K. SCHORR RCE 12955 TR. No. 30245

DATE 5-11-73

151 D-5

N571

NOTE: ALL TIES ARE L&T SET IN TOP OF CURB. ALL S&T TAGGED R.C.E. 12955



SO. CALIF. BLUE PRINT CO. 88276

Co. Engr. F.B. 4024: 125

SURVEY OF ℄ TIES F. B. _____ Pg. 1

SURVEY BY McINTIRE & QUIROS, INC. TR. No. 27605

DATE Jan. 1973

John W. McIntire LS 2602

159-037, B-1 (39)



TR. 23806 M.B. 744 - 42/46

MAY 31 1973

SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 126

SURVEY OF: ℄ TIES — F. B. ____ PG. 2

SURVEY BY: McINTIRE & QUIROS, INC. — TR. No. 27605

DATE: Jan. 1973

John W. McIntire LS 2602

39

159-037, B-1



SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 127.

SURVEY OF ℄ TIES F. B. Pg. 3

SURVEY BY McINTIRE & QUIROS, INC TR. No. 27605

DATE Jan. 1973



39

B-1

159-037

SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 128

KEMMERER ENGINEERING CO., INC.
CIVIL ENGINEERING AND SURVEYING
145 NORTH PAINTER, WHITTIER, CALIFORNIA, 698-9993

FB_____ PG_____

Survey For TR 29123 Survey By J. BARRETT Date 3-30-73

Check By_____ Date_____

SURVEY BY ROBERT R. FLORES R.C.E 11349



Co. Engr. F.B. 4024: 129

KEMMERER ENGINEERING CO., INC.
CIVIL ENGINEERING AND SURVEYING
145 NORTH PAINTER, WHITTIER, CALIFORNIA, 698-9993

FB_____ PG.

Survey For TR. 29123 Survey By J. BARRETT Date 3-30-73

Check By_____ Date_____

SURVEY BY ROBERT R. FLORES R.C.E. 11349

227

34 C-3



Co. Engr. F.B. 4024: 130

KEMMERER ENGINEERING CO., INC.
CIVIL ENGINEERING AND SURVEYING
145 NORTH PAINTER, WHITTIER, CALIFORNIA, 698-9993

FB_____ PG_____

Survey For TR. 29123 Survey By J. BARRETT Date 3-30-73

Check By_____ Date_____

SURVEY BY ROBERT R. FLORES R.C.E. 11349

227
25 34 C-3



Co. Engr. F.B. 4024: 131

KEMMERER ENGINEERING CO., INC.
CIVIL ENGINEERING AND SURVEYING
145 NORTH PAINTER, WHITTIER, CALIFORNIA, 698-9993

FB_____ PG_____

Survey For TR 29506 Survey By J. BARRETT Date 3-30-7

Check By_____ Date_____

SURVEY BY Robert R FLORES RCE 11349



Co. Engr. F.B. 4024: 132

KEMMERER ENGINEERING CO., INC.
CIVIL ENGINEERING AND SURVEYING
145 NORTH PAINTER, WHITTIER, CALIFORNIA, 698-9993

FB_____ PG_____

Survey For TR 29506 Survey By J. BARNETT Date 3-30-73

Check By_____ Date_____

SURVEY BY ROBERT R. FLORES R.C.E. 11349



Co. Engr. F.B. 4024: 133

KEMMERER ENGINEERING CO., INC.
CIVIL ENGINEERING AND SURVEYING
145 NORTH PAINTER, WHITTIER, CALIFORNIA, 698-9993

FB_____ PG_____

Survey For TR. 29506 Survey By J. BARRETT Date 3-30-7

Check By_____ Date_____

SURVEY BY ROBERT R. FLORES R.C.E. 11349



Co. Engr. F.B. 4024: 134

KEMMERER ENGINEERING CO., INC.
CIVIL ENGINEERING AND SURVEYING
145 NORTH PAINTER, WHITTIER, CALIFORNIA, 698-9993

FB_____ PG_____

Survey For TR. 29506 Survey By J. BARRETT Date 3-30-73

Check By_____ Date_____

SURVEY BY ROBERT R. FLORES R.C.E 11349



Co. Engr. F.B. 4024: 135

SURVEY OF L TIES F B NO. PAGE 1

SURVEY BY ENRIQUE ACEVEDO R.C.E. NO. 10915 TRACT NO. 30739

DATE 6-1-71



SURVEYORS SERVICE COMPANY - LOS ANGELES - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

W5 70 (36) B-5

Co. Engr. F.B. 4024: 136

SURVEY OF ℄ TIES F B NO. PAGE 2

SURVEY BY ENRIQUE ACEVEDO R.C.E. NO. 10915 TRACT NO. 30739

DATE 5-1-71

70B-3



SURVEYORS SERVICE COMPANY - LOS ANGELES - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEY OF ℄ TIES F B NO. PAGE 3

SURVEY BY ENRIQUE ACEVEDO R.C.E. NO. 10915 TRACT NO. 30739

DATE 5-1-71



SURVEYORS SERVICE COMPANY LOS ANGELES - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

70 R5

Co. Engr. F.B. 4024: 138

SURVEY OF ℄ TIES F B NO. PAGE 4

SURVEY BY ENRIQUE ACEVEDO R.C.E. NO. 10915 TRACT NO. 30739

DATE 5-1-71



70B-5

DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY - LOS ANGELES - STOCK NO. 411

Co. Engr. F.B. 4024: 139.

SURVEY OF: ℄ TIES — F B NO. ____ PAGE 5

SURVEY BY: ENRIQUE ACEVEDO R.C.E. NO. 10915 — TRACT NO. 30739

DATE: 5-1-71

70B-5



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY LOS ANGELES - STOCK NO. 411

Co. Engr. F.B. 4024: 140

SURVEY OF ℄ TIES F B NO. PAGE 6

SURVEY BY EURIQUE ACEVEDO R.C.E. NO. 10915 TRACT NO. 30739

DATE 5-1-71



705.5

SURVEYORS SERVICE COMPANY - LOS ANGELES - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Engr. F.B. 4024: 141

SURVEY OF ℄ TIES F. B. _____ PG. 7

SURVEY BY ENRIQUE ACEVEDO R.C.E. No. 10915 TR. No. 30739

DATE 5-1-71



36

U570-B-5

SO. CALIF. BLUE PRINT CO.

Co. Engr. F.B. 4024: 142

SURVEY OF ℄ Ties F B NO. PAGE

SURVEY BY Vic Case 252387 [redacted]

DATE May 1973 P.M. 3337



SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411
DO NOT EXTEND NOTES THIS SIDE OF LINE

LS 28C-1 (41)

Co. Eng. F.B. 4024: 143

SURVEY OF MUSCATEL AVENUE F.B. Pg.

SURVEY BY LOREN C. PHILLIPS L.S. 3173 TR. No. 28924

DATE JULY 10, 1973



W.S. 44 C.S.

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 144

SURVEY OF MONTEMALAGA DRIVE F B NO. ____ PAGE 1

SURVEY BY ENGINEERING SERVICE CORP. TRACT NO. 31394

DATE JULY 1973

J.K. NEWVILLE
R.C.E. 13095



ALL SET L. & T. ARE TAGGED
R.C.E. 13095

(33) 4S 2W B-2

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Eng. F.B. 4024: 145

SURVEY OF MONTEMALAGA DRIVE F B NO. PAGE 2

SURVEY BY ENGINEERING SERVICE CORP. TRACT NO. 31394

DATE JULY 1973

J.K. NEWVILLE
R.C.E. 13095



TO PAGE 1

ALL SET L. & T. ARE TAGGED
R.C.E. 13095

DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, CO... MESA ... STOCK NO. 4...

(25)

Co. Eng. F.B. 4024: 146

SURVEY OF _____ F B NO. ____ PAGE 1

SURVEY BY RICHARD S. ANGVIRE TRACT NO. 27702

DATE 7-11-73 RCE 9284



SURVEYORS SERVICE COMPANY, COSTA MESA · STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

W 56 B-2 6

W 56 L-2 20

Co. Eng. F.B. 4024:147

F B NO. PAGE 2

SURVEY BY RICHARD S. ANGVIRE, RCE 9284

TRACT No. 27702 7-11-73

W.S. 66B-C2



DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Eng. F.B. 4024: 148

SURVEY OF _____ F B NO. 3 PAGE _____

SURVEY BY RICHARD S. ANGUIRE TRACT NO. 27702

DATE 7-11-73 RCE 9284



W566 B.2 L C.2 C0

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

Co. Eng. F.B. 4024: 149

SURVEY OF ℄ TIES F B NO. PAGE 1

SURVEY BY VERPET ENGINEERING TRACT NO. 29855

DATE OCT. 23 1972

MONUMENTATION IS PLACED BY VERPET ENGINEERING UNDER THE DIRECTION OF ENRIQUE ACEVEDO RCE. 10915

MEASURED DISTANCES ARE CORRECTED TO 68°F.



SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

DO NOT EXTEND NOTES THIS SIDE OF LINE

19

W572 D-2

Co. Eng. F.B. 4024: 150

F B NO. ____ PAGE 2

MONUMENTATION IS PLACED BY VERPET ENGINEERING CO
UNDER THE DIRECTION OF ENRIQUE ACEVEDO RCE 10915
MEASURED DISTANCES ARE CORRECTED TO 68°F.

W.S. 72, D-2 (14)



DO NOT EXTEND NOTES THIS SIDE OF LINE

SURVEYORS SERVICE COMPANY, COSTA MESA - STOCK NO. 411

Co. Eng. F.B. 4024: 151

SURVEY OF ℄ TIES F. B. Pg. 3

SURVEY BY VERPET ENGINEERING TR. No. 29855

DATE OCT. 23 1972

MONUMENTATION IS PLACED BY VERPET ENGINEERING CO UNDER THE DIRECTION OF ENRIQUE ACEVEDO R.C.E. 10815
MEASURED DISTANCES ARE CORRECTED TO 68° F.



19

U572 2

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 152

F. B. _____ PG. 4 SURVEY OF ℄ TIES

TR. No. 29855 SURVEY BY VERPET ENGINEERING

DATE OCT. 23 1972

MONUMENTATION IS PLACED BY VERPET ENGINEERING CO
UNDER THE DIRECTION OF ENRIQUE ACEVEDO R.C.E. 10915
MEASURED DISTANCES ARE CORRECTED TO 68° F.

72 Q 2



Co. Eng. F.B. 4024: 153

SURVEY OF ℄ TIES F. B. Pg. 5

SURVEY BY VERPET ENGINEERING TR. NO. 29355

DATE OCT. 23 1972

MONUMENTATION IS PLACED BY VERPET ENGINEERING CO
UNDER THE DIRECTION OF ENRIQUE ACEVEDO RCE 10915
MEASURED DISTANCES ARE CORRECTED TO 68°F.



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 154

F. B. Pg. 6 SURVEY OF ℄ TIES

TR. No. 29855 SURVEY BY VERPET ENGINEERING

DATE OCT. 23 1972

MONUMENTATION IS PLACED BY VERPET ENGINEERING CO
UNDER THE DIRECTION OF ENRIQUE ACEVEDO R.C.E. 10915
MEASURED DISTANCES ARE CORRECTED TO 68°F.

72D.2



Co. Eng. F.B. 4024: 155

SURVEY OF ℄ TIES F. B.

SURVEY BY VERPET ENGINEERING

TR. No. 29855

DATE OCT. 23 1972

MONUMENTATION IS PLACED BY VERPET ENGINEERING Co
UNDER THE DIRECTION OF ENRIQUE ACEVEDO RCE. 10015
MEASURED DISTANCES ARE CORRECTED TO 68° F.

72 A-2



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 156

F. B. _____ PG. 8 SURVEY OF ℄ Ties

TR. No. 29855 SURVEY BY VERPET ENGR CO.

DATE Oct 23, 1972

Monumentation placed by Verpet Engineering Co. under direction of ENRIQUE ACEVEDO RCE 10915 Measured distances corrected to 68°F.

19

72 D 2



Co. Eng. F.B. 4024: 157

SURVEY OF ℄ TIES F. B. 113 PG. 5

SURVEY BY HIGHLAND ENGINEER TR. No. 29272

DATE 4-18-73 ROBERT K. KAMEOKA RCE 15429



INDEX MAP

SURVEYORS:
J. KRULL
B. BILMER

ALL 2" I.P.'S SET DN. 12."
ALL TIE PT.'S ARE 1" I.P. UP 2" ± UNLES OTHERWISE NOTED.
ALL DISTANCES SHOWN AS MEASURED ARE CORRECTED TO 68° F.

26

72 D-1

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 158

SURVEY OF ℄ TIES F. B. 113 PG. 6

SURVEY BY HIGHLAND ENGINEERS TR. No. 29272

DATE 4-18-73 ROBERT K. KAMEOKA RCE. 16429



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 159

SURVEY OF ¢ TIES F. B. 113 PG. 7

SURVEY BY HIGHLAND ENGINEERS TR. No. 29272

DATE 4-18-73 ROBERT K. KAMEOKA RCE. 15429

72 D-1



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 160

SURVEY OF ¢ TIES F. B. 113 PG. 8

SURVEY BY HIGHLAND ENGINEERS TR. No. 29272

DATE 4-18-73 ROBERT K. KAMEOKA RCE. 15429



22 D-1

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 161

SURVEY OF ¢ TIES F. B. 113 PG. 9

SURVEY BY HIGHLAND ENGINEERS TR. No. 29272

DATE 4-18-73 ROBERT K. KAMEOKA, RCE. 15429



26

45 72 D-1

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 162

SURVEY OF _____ F. B. _____ PG. 1 of 1

SURVEY BY Ronald W. Spindler TR. No. 29749

DATE MARCH 1973 R.C.E. 13194



114
JS 64 D-2

SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 163

SURVEY OF _____ F. B. _____ PG. 1 of 3

SURVEY BY Ronald W. Spindler TR. No. 29747

DATE March 1973 RCE. 13194



SO. CALIF. BLUE PRINT CO.

Co. Eng. F.B. 4024: 164

F. B. _____ PG. 2 of 3 SURVEY OF _____

TR. No. 29747 SURVEY BY Ronald W. Spindler

R.C.E. 13194 DATE March 1973



Co. Eng. F.B. 4024: 165

SURVEY OF _____ F. B. _____ Pg. 3 of 3

SURVEY BY Ronald W. Spindler TR. No. 29747

DATE March 1973 RCE 13194