Microsoft Access - [Response Form]

File Edit View Insert Format Records Tools Window Help

copy screen

Select a Complaint

Search by: Date / Violator's Name / Violator's Addre

Reporting a Discharge or a Connection? Discharge

Agency/Person Responding: Fire - Capt McNett

Report: Action

Report Date: 12/17/2001

ReportTime: 5:35 PM

Violator's Name: Wanda Carlson

Reported By/Name of complainant: unknown

Violator's Address: 801 2nd St., Santa Monica 90403

Address of complainant:

Incident Address: 801 2nd St., Santa Monica 90403

Phone of complainant:

Violator's E-mail:

Permit Number:

Violator's Phone:

On-Site Contact:

Nature of Complaint: Transmission fluid leak from 1984 Pontiac vehicle.

Description of conditions noted by Inspector upon arrival: transmission fluid leaking from vehicle

Report Material
- Hazardous
- Waste Water (Sewage)
- Oil/Grease
- Sediment
- Other
- Unknown

Other Report Material: transmission fluid

Land Use
- Residential
- Industrial
- Commercial
- Public

Estimated Quantity:

Connection Found: ☐

Description of connection:

Source Investigation Conducted: ☐

Source Identified: ☑

Entered Storm Drainsystem/receiving waters: ☐

Source of discharge or owner of connection: Leaking vehicle

First | Previous | Next | Last | New | Refresh Data | Save | Cancel | Print this Record | Close

Form View

Microsoft Access - [Response Form]

File Edit View Insert Format Records Tools Window Help

copy screen

Select a Complaint

Search by: Date Violator's Name Violator's Addres

Reporting a Discharge or a Connection? Discharge

Agency/Person Responding Fire - Capt. McNett

Report | Action

ReferredTo

Date Complaint Resolved 02/17/2004

Aagency Name: City Fire Dept.

Phone:

City:

Dept.:

Resolution of illicit discharges

- [ ] Resulted in no evidence of discharge.
- [ ] Determined to be conditionally exempt.
- [ ] Exempt or in compliance and the source identified.
- [x] Discontinued / cleaned up voluntarily or through enforcement and the source was identified.
- [ ] Cleaned up but the source could not be identified.
- [ ] Resulted in enforcement action.

Resolution of illicit connection

- [ ] Converted exempt discharges to NPDES permitted
- [ ] Converted illicit discharges that were terminated
- [ ] Was removed
- [ ] Resulted in enforcement actions
- [ ] Resulted in other actions

Nature of Resolution: Company used absorbents to pick up fluid. Company left absorbents on spill to absorb further and provide traction until tow company arrived. Advised to call tow truck immediately.

First | Previous | Next | Last | New | Refresh Data | Save | Cancel | Print this Record | Close

Form View