*HFIA

c/s @ 2858 St. James PL. Dirt

ALTADENA / LACO

VICINITY MAP

NOT TO SCALE



NOTE:

- HARDSET SOUTH-CK
- TRAFFIC CONTROL REQ.
- NO P.T.C. REQ.
- E TO C-13', LTD, PB
- POSSIBLE CURB REPAIR (1' X 1')
- TREE TRIMMING REQ.

REQUIRED PERMITS:
- TRAFFIC CONTROL PERMIT REQ.
- EXCAVATION PERMIT REQ.

SOUTHERN CALIFORNIA EDISON
An EDISON INTERNATIONAL Company

NOTES:

HAND SET: NO
JOINT MEET: NO
TRUCK ACCESS: YES
CONTACT CATV: NO
PAVEMENT REPAIR: YES
JOINT ANCHOR: NO
ENVIRONMENTAL/ REAL PROP. REVIEW: NO

If changes to JPA are req'd i.e., Cut vs. PTD, or location change *contact Joint Utility prior to construction

UTILITY: HLA
ENGINEER: JANET CHIRRICK
PHONE: 559-739-6072
DATE:
INSPECTED BY:
DATE INSPECTED: STA: 3 & 4

SECO 16KV % ARROYO SUB

NOT TO SCALE

DISTRICT	PROJ. MGR.	PLANNER	BUDGET ITEM	YEAR
27 – MONROVIA	JOHN RODRIGUEZ PHONE 909-469-0219	RANDY CHAVERS PHONE 909-303-3493	480	2014

FOREMAN	TRUCK NO.	P/E	INVENTORY MAP NO.	THOMAS GUIDE	GRID NO.	DESIGN NO.
			081-077D	636-A5	000	569323_0.01

CSD 140 Y___ N___	BY-PASS CODE	EXISTING ___ CHANGE TO ___	TLM CHECKED ___ %LOAD	J.P.A. NO. E6027-405929189	ASSOCIATED DESIGN NO.

PRODUCT/SAP NO.	PRODUCT/SAP NO.	PRODUCT/SAP NO.
815070- DET POLE REPLACEMENT		

TYPE	APPROVED BY	DATE	CHECKED BY	DRAWN BY	PAX #
		3/7/14		IMS/SR	909-303-3493

PROPOSED CONSTRUCTION (LOCATION)
DETERIORATED POLE REPLACEMENT
ST JAMES E/S 4' S/O MARIGOLD EXTD
LA CANADA FLINTRIDGE

SHEET ___ OF ___

JOB NO. 569323_0.01

Southern California Edison Company

PAGE NO. 2 - 4 J.P. AUTH. NO. E6027-405929189

POLE NO.	Pole Length / Anchor Size	Year Set	Pole Trt / Class / Anchor Direct.	Record 16KV E	Record HLA	Record VZ	Record	Proposed 16KV E	Proposed HLA	Proposed VZ	Proposed	Proposed	Item No.	LOCATION AND NATURE OF WORK If not in accordance with Joint Pole agreement and routine-state reasons.	
3								C-13'						E TO REPLACE POLE SEC. 7.11, 7.4, 1.2, 19.4, 19.6, 10.8	1
1992861E	40	73	FT		20'			PB LTD						ST JAMES E/S 4' S/O MARIGOLD EXT, ALTADENA	2
								1/2(1)					19A	CUT & KICK	3
								1/2(1)					13C	TRAFFIC CONTROL REQ'D- COST TO FOLLOW	4
								1/2(1)					13B	TREE TRIM REQ'D	5
								1/2(1)					10C	CC REPAIR (1'X1')	6
								1					78A	CATV J-HOOK W/GRIP (CH) (HSO-TN)	7
								1					78A	COMM J-HOOK W/GRIP (HLA)	8
								1					78B	ADD GRIP (COMM)	9
															10
															11
															12
4															13
1992861E	35		FT 4					29-9	20-2					ST JAMES E/S 5' S/O MARIGOLD EXT, ALTADENA	14
														HARDSET SOUTH-CK	15
															16
															17
															18
															19

OLE LEGEND:
= PULL
B = POLE BUTT
= TRANSPORT
= SALVAGE
= DISPOSE
N = TENANT

L = LOWER CUT
C(XX)= FOOTAGE CUT
SCZ = SAFETY CLEARANCE ZONE

ANCHOR LEGEND:
AR = ANCHOR/ARM REMOVED
AT = ANCHOR/ARM TRANSFERRED

Show Quantity of Items to be billed in the Column of Party to be Paid.

GEOGRAPHICAL LOCATION

ALTADENA
COMMUNITY

Rev. Jan 2010