

**Vincent
Kevin
Kelly
&
Assoc.
Inc.** structural
engineering
consultants
3400 Airport Avenue, ste 99
Santa Monica, Ca 90405
310.397.3700 tel
310.397.3700 fax
vkk@vkkengineering.com

Vincent Kevin Kelly, P.E.
President
Arash Mozaffarian, M.S., P.E.
Director Engineering
Structural Engineering Associates
Edgar Diaz,
Liguang Xue, M.S., P.E.
Doree Thompson
Mary Olson

May 6, 2014

Clear Channel Outdoor, Inc
19320 Harborgate Way
Torrance, CA 90501

Attn: Mr. Dan Voorhees

RE: Structural Observation
Free-Standing 12X25 Sign Structure
4323 Compton Blvd.
County of Los Angeles, CA

VKK Ref#14C56

Dear Dan,

Pursuant to your request we reviewed the sign structure based on the information presented by your office. The existing sign structure, and columns appear to be in good condition. In addition the restored decks and sign faces are adequate and in accordance with the original sign permit.

As a general recommendation we suggest that the sign structure and columns undergo periodic maintenance to limit the effects of corrosion by using proper painting methods.


If you should have any questions please do not hesitate to contact our office directly.

Respectfully submitted,

Vincent Kevin Kelly & Assoc., Inc

Vincent Kevin Kelly





**Vincent
Kevin
Kelly
&
Assoc.
Inc.**

structural
engineering
consultants
3400 Airport Avenue, ste 99
Santa Monica, Ca 90405
310.397.3700 tel
310.397.3700 fax
vkk@vkkengineering.com

Vincent Kevin Kelly, P.E.

President

Arash Mozaffarian, M.S., P.E.
Director Engineering

Structural Engineering Associates

Edgar Diaz,
Liguang Xue, M.S., P.E.
Doree Thompson
Mary Olson

May 6, 2014

Clear Channel Outdoor, Inc
19320 Harborgate Way
Torrance, CA 90501

Attn: Mr. Dan Voorhees

RE: Structural Observation
Free-Standing 12X25 Sign Structure
4323 Compton Blvd.
County of Los Angeles, CA

VKK Ref#14C56

Dear Dan,

Pursuant to your request we reviewed the sign structure based on the information presented by your office. The existing sign structure, and columns appear to be in good condition. In addition the restored decks and sign faces are adequate and in accordance with the original sign permit.

As a general recommendation we suggest that the sign structure and columns undergo periodic maintenance to limit the effects of corrosion by using proper painting methods.

If you should have any questions please do not hesitate to contact our office directly.

Respectfully submitted,

Vincent Kevin Kelly & Assoc., Inc

Vincent Kevin Kelly

