Form 271 11M 1-32

"Y" IN R/W

Permit No. 36342

5235-012-058

P ~~C.I.~~ No. 321-100

Address 207-1/2 N. Kern Ave

Lot 36 ?

Block No.2 Tract Maravilla Park

Contractor Pete Caldern

Owner "

Sta. of House Connection 5+79.8

~~Sta. of "Y"~~ 48.2' No. from MH in ~~Riggin~~ First St. Ave

Between Brooklyn

and Riggin Ave

Date Permit Issued 9-11-1937

Date Inspected 9/21-37

By Peare Inspector

Remarks Add inspection
straighten Line install
C.O. at soil Pipe con test Plg
No Good Bustamonte working
Help in owner on Job.

ADDITIONAL INSPECTION NO. 7725

Over



9/23/37 Peare
add inspection
Reverse Grade to Rear House
Con- water stands 2" Deep
FIX Leaks install 1/8 Bend on Riser
Bad Pinched Joint

ADDITIONAL INSPECTION NO. 7747
9/28/37 Peare
Add inspection FIX Leaks
in Front of Rear House Back Fill
Rest of Line

~~ADDITIONAL INSPECTION NO.~~
11-4-37 - OK Peare
Finished