7BA888A CE8888 3-68

APPLICATION FOR BUILDING PERMIT

1

COUNTY OF LOS ANGELES
DEPARTMENT OF COUNTY ENGINEER
BUILDING AND SAFETY DIVISION
JOHN A. LAMBIE, COUNTY ENGINEER
COLEMAN W. JENKINS, SUPT. OF BUILDING

BUILDING ADDRESS: 20518 W Callon Dr
LOCALITY: Topanga Cyn
NEAREST CROSS ST.: Cheney Dr.

DISTRICT NO.: 9.2 | GROUP: I | TYPE CONST.: V | PROCESSED BY:

STATISTICAL CLASSIFICATION: CLASS NO. 1 DWELL. UNITS 1 | SEWER MAP: BK PG

USE ZONE: R-1 10M | MAP NO.: 4439 | SPECIAL CONDITIONS: PP. 17488

BLDG. SETBACK FROM FRONT PROP. LINE OF: CALLON (STREET)

TYPE OF HIGHWAY	EXISTING WIDTH	SETBACK FROM C.L.	HIGHWAY	+	YARD	=	TOTAL
Loc	50	—	5	+	20	=	25

BLDG. SETBACK FROM SIDE PROP. LINE OF: _____ (STREET)

TYPE OF HIGHWAY	EXISTING WIDTH	SETBACK FROM C.L.	HIGHWAY	+	YARD	=	TOTAL
				+		=	

CORNER CUTOFF YES ☐ NO ☐

FOR APPLICANT TO FILL IN
(Print or type only)

BUILDING ADDRESS:

LOT NO.: 13 P CL 5 17, 15, 19, 20 BLOCK:

TRACT: No 3729

SIZE OF LOT: 50x112.6 | NO. OF BLDGS. NOW ON LOT: None

LOC. OF EXISTING BLDG.: — —

OWNER: Ron Sumpston | TEL. NO.: 455-2362

ADDRESS: 1362 Old Topanga Rd.

CITY: Topanga

ARCHITECT OR ENGINEER: Same as | TEL. NO.: Owner

ADDRESS:

CONTRACTOR: Ron Sumpston | TEL. NO.: Same | LIC. NO.:

ADDRESS:

CITY: | LIC. CLASS:

DESCRIPTION OF WORK

(NEW) ADD ALTER REPAIR DEMOLISH

SQ. FT. SIZE: 1480 + 320 | NO. OF STORIES: 1 | NO. OF FAMILIES: 1

USE OF STRUCTURE: I I

Home & CARPORT

SIGNATURE OF APPLICANT: Ronald Sumpston

VALUATION $: 12,800

P.C. FEE $: 30.00 | PMT. FEE $:

I HEREBY ACKNOWLEDGE THAT I HAVE READ THIS APPLICATION AND STATE THAT THE ABOVE IS CORRECT AND AGREE TO COMPLY WITH ALL COUNTY ORDINANCES AND STATE LAWS REGULATING BUILDING CONSTRUCTION. I CERTIFY THAT IN DOING THE WORK AUTHORIZED HEREBY I WILL NOT EMPLOY ANY PERSON IN VIOLATION OF THE LABOR CODE OF THE STATE OF CALIFORNIA RELATING TO WORKMEN'S COMPENSATION INSURANCE.

SIGNATURE OF PERMITTEE: Owner

ADDRESS:

SEE REVERSE SIDE FOR SPECIAL APPROVALS

Exp Nov 5-25-69 by
OS Hom. Plans
Must be lined up
to check since 1-8-69

APPROVALS	DATE	INSPECTOR'S SIGNATURE
FOUNDATION: LOCATION FORMS, MATERIALS		
FRAME: FIRESTOPS BRACING, BOLTS		
FURNACE: LOCATION GAS VENT, DUCTS		
LATH, INT.		
LATH, EXT.		
HOUSE NUMBER COR. PERT AND POSTED		
FINAL		

INSPECTOR COPY

JOHN F. LEWIS, PRINCIPAL STRUCTURAL ENGINEER

PLAN CHECK VALIDATION CK NO. CASH

PERMIT VALIDATION CK NO. CASH

671580 24 3 30.00

PGA300-11-68

GEOLOGIC REVIEW SHEET

ENGINEERING GEOLOGY SECTION
DEPARTMENT OF COUNTY ENGINEER
LOS ANGELES COUNTY

SHEET 1 OF 1

Site Address 20518 West Callon Drive
Location Topanga
Developer/Owner Ronald Swepston
Engineer --
Geologist --
Soils Engineer --

DISTRIBUTION:
- [ ] Plan Check
- [x] Dist. Engineer
- [ ] Grading Section
- [ ] File
- [ ] Geologist
- [ ] Soils Engineer
- [ ] Site Engineer

Review of: DATE OR PLAN CHECK NO.
- [ ] Grading Plan
- [x] Building Plan 7158
- [ ] Geologic Report
- [ ] Soils Report
- [ ] Other

Action:
- [ ] Plan is approved
- [ ] Plan is not approved (See Below)
- [ ] Submit plans for recheck
- [x] Plan approved subject to conditions below

Remarks: The structure should be located away from the slope between Callon Drive and the structure.

Checked _____ Approved R. E. Grad Date 1-9-69