GREASE TRAP Permit No. 5638

Pd. 2/17/28 C.I. No. 151

ADDITIONAL INSPECTION NO. 567

No. 3634 E. 1st. St.

Lot W. Pov. of 1 Block 28 5232-016-046

Tract East Side

Contractor Zambica & Gekawe

Owner E. Fareri

Sta. of House Connection 0+74.6

~~Sta. of "Y"~~ 74.6 E. of Cove Mtl. chk

Between Cov. Townsend

and

Date Permit Issued 1-20-28

Date Inspected 1-27-28

By Feare Inspector

Remarks Note this Job O.K. except Rear House occupies Part of (2) Lots (notice to install) Grease trap 3636 east 1st by March 1st - 27 2nd inspection

OK 2/21/28



Townsend

134 8

53

1 pt