ATTACHMENT A
MEMO 20.12

INVESTIGATION REPORT
BUILDING AND SAFETY/LAND DEVELOPMENT DIVISION

Location of Problem: 3022 E. FLOWER ST

Locality: WALNUT PARK

Description of Problem: BATHROOM ADDED TO GARAGE ~~HOUSE~~ - NO PERMITS

Requested by: ~~OWNER~~ FRANCISCO RIBAS Phone: (213) 588-1823

Address:

Request call back after investigation? Yes ☐ No ☐

Received by: J. RODGERS Date: 8-8-96

Assigned/Referred to: J. RODGERS Date: 8-8-96

Report of Investigation: BATH ROOM AND A STORAGE & PATIO ADDITION TO GARAGE NO PERMITS FOR ANY OF THE CONSTRUCTION WORK FOR THE BATH ROOM, PATIO OR STORAGE ROOM. A STOP WORK NOTICE LEFT AT THE JOB SITE.

Investigator: J. RODGERS Title: BLDG INSP Date: 8-13-96

Copy Sent to: REC PLANNING Title: Date: 8-14-96

Report Phoned to: Title: Date:

DISKAM/AM20.12A/07/95

ADDRESS 3022 E. FLOWER

OWNER

STOP ALL WORK

You are in violation with the provisions of the County Ordinance as indicated below

- ✓ Building Code
- ✓ Plumbing Code
- ✓ Mechanical Code
- ✓ Electrical Code
- ✓ Zoning Ordinances
- Grading Code



REWIRE ST WITH SHOWER

DESCRIPTION BATH ADDITION TO GARAGE
NO PERMITS ON FILE FOR ADDITION.
ALSO PATIO & STORAGE ADDITION TO GARAGE
NO PERMITS ON FILE FOR CONSTRUCTION WORK DONE.
PLOT PLAN

✓ Submit plans for the work within 10 days to the office listed above and apply for a plan check for the required Permit

✓ Obtain a Permit within 10 days for the work at the office listed above.

✓ A referral ~~has been~~ WILL BE made to the Enforcement Section of the Department of Regional Planning.

8-13-96 G. RODGERS

DATE INSPECTOR'S SIGNATURE

Location 3022 E. Flower Date 8-13-96

Complaint BATH ADDITION TO GARAGE, PATIO AND STORAGE ADDITION TO GARAGE (NO PERMITS).

Requested by COUNTY of LOS ANGELES, BUILDING & SAFETY (Complainant)

Address 7807 Compton Ave. Suite # 200 Phone (213) 586-6537

Los Angeles, Ca. 90001

Submitted by Sr.B.E.I. [illegible] Dept. Firestone Dist. Office

Address 7807 Compton Ave. Suite # 200 Phone (213) 586-6537

Los Angeles, Ca. 90001

AP:REQST