



INVESTIGATION REPORT
BUILDING AND SAFETY/LAND DEVELOPMENT DIVISION

Location of Problem 3050 Audubon

Locality _____

Description of problem:

- VACANT LOT
- TRASH, JUNK, DEBRIS IN YARD AREAS
- DISCARDED FURNITURE- APPLIANCES
- VACANT HOUSE
- OVERGROWN VEGETATION
- _____ INOPERABLE VEHICLE(S)

Owners built a patio attached to the fence. Too close to the neighbors house

Requested by:

Request call back after investigation? Yes [] No []

Received by: [Signature] Date: 1-18-00
Assigned/Referred to: _____ Date: _____

Report of Investigation: _____

Investigator: _____ Title: _____ Date: _____
Copy Sent to: _____ Title: _____ Date: _____
Report Phoned to: _____ Title: _____ Date: _____



INVESTIGATION REPORT
BUILDING AND SAFETY/LAND DEVELOPMENT DIVISION

Location of Problem 3050 Cudahy

Locality _____

Description of problem:

- VACANT LOT
- TRASH, JUNK, DEBRIS IN YARD AREAS
- DISCARDED FURNITURE- APPLIANCES
- VACANT HOUSE
- OVERGROWN VEGETATION
- INOPERABLE VEHICLE(S)

Made Patio to the fence
construction inside the
Residence

Requested by:

Request call back after investigation? Yes No

Received by: Helen Mc Gregor Date: 11/8/99

Assigned/Referred to: _____ Date: _____

Report of Investigation: _____

Investigator: _____ Title: _____ Date: _____

Copy Sent to: _____ Title: _____ Date: _____

Report Phoned to: _____ Title: _____ Date: _____

DISKAM/AM20.12A/07/95

JOB ADDRESS 3050 E. CUDAHY S
OWNER _____

NOTICE OF VIOLATION

The work performed is in violation of the Ordinance(s) indicated below:

- Building Code _____ Plumbing Code _____
 - Mechanical Code _____ Electrical Code _____
 - Grading Code _____ Zoning Code _____
- PATIO / ROOM ADDED

DESCRIPTION: ILLEGAL BLDG STRUCTURE CONSTRUCTED WITHOUT BUILDING PERMITS OR PLANS. ALSO TO CLOSE TO THE (EAST SIDE) PROPERTY LINE (CONSTRUCTED ON THE SIDE PROPERTY LINE)

- STOP ALL WORK**
- Submit plans for the cited work within 10 days to the office listed above and apply for a plan check for the required permit(s).
- Obtain permit(s) within 10 days at the office listed above for the cited work.
- A referral has been made to the Enforcement Section of the Department of Regional Planning.

1-19-2000 DATE [Signature] INSPECTOR'S SIGNATURE

JOB ADDRESS 3050 E. CUDAHY SP
OWNER _____

NOTICE OF VIOLATION

The work performed is in violation of the Ordinance(s) indicated below:

- Building Code _____ Plumbing Code _____
- _____ Mechanical Code _____ Electrical Code _____
- _____ Grading Code _____ Zoning Code _____

DESCRIPTION: ILLEGAL PATIO AND OR CARPORT CONSTRUCTED IN THE SIDE YARD SETBACK, ALSO ILLEGAL CONSTRUCTION ON THE INTERIOR OF THE HOUSE. NO PERMITS OR PLANS.

- STOP ALL WORK**
- Submit plans for the cited work within 10 days to the office listed above and apply for a plan check for the required permit(s).
- Obtain permit(s) within 10 days at the office listed above for the cited work.
- A referral has been made to the Enforcement Section of the Department of Regional Planning.

1-19-99 DATE [Signature] INSPECTOR'S SIGNATURE
G. RODGERS