


# Surface Gas Emissions and Number of Odor Complaints - Sunshine Canyon Landfill



60 vertical gas wells and 27 pumps were installed.

14 vertical gas wells installed.

Flare 10 became operational.

Gas well was damaged.

14 vertical gas wells were installed.

Ponded water, erosional rills, damaged protective soil layer, and trash exposure from a storm event were observed.

From Dec. 2013 to April 2014, 30 vertical gas wells and 25 pumps were installed.

9,500 linear feet of gas lines and 1,900 linear feet of header lines were installed.

24 vertical gas wells were installed.

July 21 - startup of the Gas-to-Energy facility commenced.

September 1 - Gas-to-Energy facility became fully operational.

September 16 - approximately 100' x 100' area of settlement within the existing refuse area on the City South portion was observed. Remediation of the area was completed the next day.

29 vertical gas wells were installed, an 18-inch header was installed on the City-side, and well dewatering program was upgraded.

Trash exposure on several occasions were observed due to intense rainfall.


Nov. 3 - trash exposure was observed due to improper covering of trash from the previous Saturday evening.

11 vertical gas wells were installed.

Note: 1.) Number of complaints are based on AQMD's Complaint Summary Monthly Reports.  
 2.) Number of surface gas exceedances is based on Republic Services' Rule 1150.1 Quarterly Monitoring Reports


# Surface Gas Emissions and Number of Odor Complaints - Sunshine Canyon Landfill

◆ Number of Odor Complaints      ● Number of Surface Gas Exceedances (>500 ppm)



Note: 1.) Number of complaints are based on AQMD's Complaint Summary Monthly Reports.  
 2.) Number of surface gas exceedances is based on Republic Services' Rule 1150.1 Quarterly Monitoring Reports

# Leachate Collected and Number of Odor Complaints - Sunshine Canyon Landfill



60 vertical gas wells and 27 pumps were installed.

14 vertical gas wells installed.

Flare 10 became operational.

Gas well was damaged.

14 vertical gas wells were installed.

Ponded water, erosional rills, damaged protective soil layer, and trash exposure from a storm event were observed.

From Dec. 2013 to April 2014, 30 vertical gas wells and 25 pumps were installed.

9,500 linear feet of gas lines and 1,900 linear feet of header lines were installed.

24 vertical gas wells were installed.

July 21 - startup of the Gas-to-Energy facility commenced.

September 1 - Gas-to-Energy facility became fully operational.

September 16 - approximately 100' x 100' area of settlement within the existing refuse area on the City South portion was observed. Remediation of the area was completed the next day.

29 vertical gas wells were installed, an 18-inch header was installed on the City-side, and well dewatering program was upgraded.


Trash exposure on several occasions were observed due to intense rainfall.

Nov. 3 - trash exposure was observed due to improper covering of trash from the previous Saturday evening.

11 vertical gas wells were installed.

Note: 1.) Number of complaints are based on AQMD's Complaint Summary Monthly Reports.  
 2.) Leachate collected is based on Republic Services' Summary of Water Sources Quarterly Reports to the SCL-LEA.

# Leachate Collected and Number of Odor Complaints - Sunshine Canyon Landfill



Note: 1.) Number of complaints are based on AQMD's Complaint Summary Monthly Reports.  
 2.) Leachate collected is based on Republic Services' Summary of Water Sources Quarterly Reports to the SCL-LEA.