CSB 3|10|5

A|1 OF A|4

PHOTO RECONAISSANCE MAP OF THE SAN ANDREAS FAULT ZONE

DEPARTMENT OF COUNTY ENGINEER

JOHN A. LAMBIE
COUNTY ENGINEER

B-3105

DEPUTY

Recently active breaks, dashed where inferred. After D.C. Ross (1969)

Zone of faulting as interpreted from aerial photographs. By Engineering Geology Section
R. Waldbaum

SAN ANTONIO HEIGHTS
CUCAMONGA
UPLAND
CLAREMONT
COLLEGE HEIGHTS
ONTARIO
POMONA
SANTA ANA DEL CHINO
(ADDITION TO)

* GEOLOGICAL SURVEY, FEDERAL CENTER DENVER, COLORADO OR WASHINGTON 25, D. C.
FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

1954



CSB 3105

A 2 OF A 4



CSB 3105

A3 OF A4

CSB 3105

A4 OF A4