

Distribution Repair Order

Information:CAD ID: GO 072414-00415Incident Date: 07/24/2014 Time: 13:46Structure No: 427150HRO Date: 07/24/2014 Time: 13:46Reported by: Plavsic,Radio No: 9276Cell Number: (323) 313 6730Problem: Pole OtherCause: OtherCircuit: VAN WICKCode 18620Sub: HowardLocation: 10616 S WESTERN AVE, LOS ANGELESAccess: StreetSeq No: 90845

Foreman: _____

Radio No: _____

Cell Number: _____

Duration: 8Crew Size: 4Crews Needed: 1Crew Type: DISTRIBUTIONEnvironmental Release? NoEnvironmental Other? No District Notified? NoTree Crew Needed? NoGrounding Needed for Tree Crew? No**Load Off (Individual or Downstream):**NO LOAD OFF, HAZARD**Other Departments:** TeleComm Transmission Other Utility Other _____**Equipment Needed:** Double/Tub Bucket Arrowboard Flatbed EasyHauler Y2K Ped Control Snow Cat Fork Lift Auger Truck P/L Dolly Air Ops Power Dolly UG Van P/L Pole Dolly Four Wheel Drive Crane**Material:**1-No Material Needed**# of Attachments- 2****Remarks:(Status of Line, Access Instructions, Special Instructions)**

CREW TO ISOLATE SPAN OF PRIMARY WEST OF 427150H FOR CUSTOMER REPAIRS. TRUCK ACCESS OK. CUSTOMER NAME DAVID 661-816-6512

eMobile - [VAN WICK (4.00KV) 18620 / Howard 6/30/2014 10:25:24 AM # 1]

File Home Maps Manuals Forms Inbox Search Work Timesheet Reports Help Windows Exit

View/Structure
A1 427150H

0059899

S WESTERN

W 106TH

S MANHATTAN PL

0059899
150
427150H

6 C 2380534E 910872E 2364587E 4445643E 6 C

W 107TH

724066E 6 C 724066E 6B3165E AB 6 C

W 108TH

2247549E 6 C BB3B73E PPD0104 659305E 659307E 6 C

F14326B

Start eDataTool Ver... DeLorme Stree... 2 Fw: Trouble O... RepairOrder 2... 1:52 PM



