



SUNSHINE CANYON LANDFILL VEGETATION STATUS



FPRS Update November 18, 2010



CITY SIDE SAGE MITIGATION



CITY SIDE SAGE MITIGATION

Photo 1




Photo 1. Facing west at lower deck of vegetated areas dominated by non-natives weeds and barren areas consisting of compacted and heavily disturbed soils.

Photo 2





Photo 2. View of native Phacelia sp. within the lower deck that is surrounded by non-native mustard and Russian thistle.

CITY SIDE SAGE MITIGATION



CITY SIDE SAGE MITIGATION




Photo 3

Photo 3. Facing east at middle deck of vegetated areas consisting of good native species composition. Presence of non-native species is less at middle deck compared to the lower and upper decks.





Photo 4

Photo 4. Facing south at north-facing bench below upper deck. Native plants have established and are often taller than non-natives; however, brome grasses and other weeds are co-dominant.

COUNTY SIDE SAGE MITIGATION



COUNTY SIDE SAGE MITIGATION



Photo 1. Facing west at established coastal sage scrub and adjacent areas where germination and establishment has been problematic.

COUNTY SIDE SAGE MITIGATION

Photo 2




Photo 2. Facing southwest at coastal sage scrub dominated with California buckwheat on the County sage slopes.

COUNTY SIDE SAGE MITIGATION



Photo 3

Photo 3. Facing west at coastal sage scrub dominated with California buckwheat on the county sage slopes.

COUNTY SIDE SAGE MITIGATION



COUNTY SIDE SAGE MITIGATION



Photo 4

Photo 4. View of native species that have successfully established on the county sage slopes.

QUESTIONS & COMMENTS