
FIGURE 1-1 Bioassessment Monitoring Locations
2011-2012 Annual Stormwater Monitoring Report
Detail Area
Palmdale
SMC08540
SMC04956
Santa Clarita
SMC01164
VENTURA COUNTY
Simi Valley
Thousand Oaks
LOS ANGELES COUNTY
Burbank
Glendale
6
Pasadena
LALT503
7
Los Angeles
SMC11384
LALT501
SMC12814
SMC04750
SMC05902
Malibu
Pacific Ocean
East Los Angeles
El Monte
West Covina
5, SGLT-506
Pomona
SGUT-501
SGUT-504
SGUT-505
Inglewood
Downey
LALT500
Norwalk
Fullerton
ORANGE COUNTY
SAN BERNARDINO COUNTY
19
8,LALT502
Torrance
Anaheim
Orange
Long Beach
Garden Grove
Santa Ana
Irvine
Huntington Beach
Bioassessment Stations
Lined Channel
Unlined Channel
Northern Boundary LACFCD
County Boundary
Streams
Note: Sites demarked with (SMC) also fulfill SMC monitoring requirements.
Watershed Management Areas
ANTELOPE VALLEY
CALLEGUAS
DOMINGUEZ CHANNEL
LOS ANGELES RIVER
MOJAVE
SAN GABRIEL RIVER
SANTA ANA RIVER
SANTA CLARA
SANTA MONICA BAY
0 3.5 7 Miles
N
WESTON SOLUTIONS